




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5740C
Case Reference Number	BUS/04/21/1061
Registration Date	16/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	He Yang
Type of Accident	Side Swipe
Accident Date and Time	29/4/2021 7:16 PM
Accident Reported Date and Time	29/4/2021 9:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110867
Special Instruction to ARC,if any	SG5740C-LEFT FRONT PORTION SJQ2868S (TP) INSURED WITH NTUC
Prepared Date and Time	7/5/2021 6:30 PM
Chassis Number	WMAA95ZZXG7003176
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$538.00	\$446.00
Total Spare Part Cost	\$2,507.54	\$1,154.59
Total Other Cost	\$0.00	(\$195.20)
TOTAL COST	\$3,840.54	\$1,935.39
Lump Sum Total	\$3,850.00	\$1,950.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	07/05/2021 6:34 PM	10/05/2021 7:57 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR					Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00					\$530.00	
Total Labour			\$795.00					\$530.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC					Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$538.00					\$446.00	
Total Spray Painting & Panel Beating			\$538.00					\$446.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC					Adjusted by Surveyor, if applicable	
Lump Sum Adjustment by Surveyor			\$0.00					(\$195.20)	
Total Other Costs			\$0.00					(\$195.20)	
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153			FRONT HEADLAMP PANEL LH	1.00	\$974.70	100.00	\$0.00	Replace	Repair
6010304			FRONT HEADLAMP LH	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
6010306			FRONT AUX HEADLAMP FLASHER LH	0.00	\$904.40	0.00	\$0.00	Replace	Not Given
Total					\$3,482.70		\$1,443.24		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									