

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Main	TO REPSRAY FRONT BUMPER	378.00	200 /	
2 Main	TO RESPRAY FRONT FENDER LH	378.00	200 /	
3 Main	TO RESPRAY RIM	180.00	0 ✕	XAN
4 Main	TO RESPRAY FRONT DOOR LH	378.00	200 /	
Total:		1,314.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	XAN
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20 /	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60 /	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88 /	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30 /	
Total:			716.88	406.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,721.13	1,268.52
Total Labour Cost:	845.00	400.00
Total Spray Painting	1,314.00	600.00
Other	716.88	406.88
Overall Total	7,597.01	2,675.40
Lump Sum Repair Option	☐	☒
Lump Sum Total	7,600.00	2,700.00
Surveyor Approved Amount		2,700.00
No of Repair Days*	6	5
Remarks	-	lump sum repair / after paint photo
Surveyor Name		Rasul