

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
8 Kaki Bukit Ave 4 #08-45/46
Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444

TO	: ERGO	DATE	: 6-May-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	: SXXXX564H	VEHICLE NO.	: SKJ8403K
ADDRESS	: Denise	MODEL / MAKE	: BMW 316i
TEL. NO.	:	CHASSIS NO.	: WBA3A120X0J720426
OWNER INSUANCE		ACCIDENT DETAIL	
POLICY NO.	: NTUC	DATE	: 1-May-21
	: 5116445950	TIME	: 15:40HRS

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILLAMP LH/RH	2	\$ 390.05	\$ 780.10
2	REAR TAILLAMP GARNISH LH/RH	2	\$ 52.00	\$ 104.00
3	REAR TAILLAMP LOWER BRACKET LH/RH	2	\$ 43.00	\$ 86.00
4	REAR BUMPER	1	\$ 1,378.85	\$ 1,378.85
5	REAR BUMPER REVERSE SENSOR	4	\$ 238.05	\$ 952.20
6	REAR BUMPER REVERSE SENSOR RUBBER SEAL	4	\$ 8.10	\$ 32.40
7	REAR BUMPER REVERSE SENSOR HOLDER	4	\$ 25.75	\$ 103.00
8	REAR BUMPER REVERSE SENSOR WIRE HARNESS SET	1	\$ 223.20	\$ 223.20
9	REAR BUMPER REFLECTOR LH/RH	2	\$ 37.45	\$ 74.90
10	REAR BUMPER TOW HOOK COVER	1	\$ 43.50	\$ 43.50
11	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 73.00	\$ 146.00
12	REAR BUMPER TOP RETAINER	1	\$ 88.00	\$ 88.00
13	REAR BUMPER LOWER RETAINER LH/RH	2	\$ 88.00	\$ 176.00
14	REAR BUMPER REINFORCEMENT	1	\$ 470.25	\$ 470.25
15	REAR BUMPER LOWER UNDER SIDE COVER RH	1	\$ 121.00	\$ 121.00

TOTAL PRICE \$ 4,779.40
LESS -5% \$ (238.97)
SUB TOTAL PRICE \$ 4,540.43

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS SET	1	\$ 60.00	\$ 60.00
2	REAR BOOT LID NUMBER PLATE WITH CASING SET	1	\$ 85.00	\$ 85.00
3	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00
4	REAR BUMPER RIVET SET	1	\$ 60.00	\$ 60.00

TOTAL

\$ 285.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,250.00	200	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	250	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 75.00	x	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 250.00	x	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 120.00	50	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 380.00	x	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 280.00	x	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	x	

TOTAL

\$ 3,515.00

530

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,825.43
 TOTAL LABOUR COST : \$ 3,515.00
 TOTAL REPAIR COST : \$ 8,340.43

Adrian L
 L/S 10/05/21.
 02 Days

APPROVED DETAILS

NO. OF REPAIR DAYS

DAYS

REPAIR UNDER

PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY
 SURVEYED BY / FROM
 CONTACT NUMBER
 FAX NUMBER
 EMAIL ADDRESS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 2441.31

L/S 1-9K ✓