

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005636/KRA3Q2
Date: 27/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000002176
Claimant Vehicle No :	SJJ1898Z	Insured Vehicle No :	SMR6792J
Date of Loss:	06/05/2021	Nature of Claim:	TP
		Claim No:	7971582197SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1898Z		
Make & Model:	HONDA VEZEL HYBRID, 1.5 RS (A)	Engine No:	LEB5962612
Reg. Date:	06/12/2017 (Man. Year: 2017)	Chassis No:	RU31262595
Colour:	Metallic Red	Odometer:	49067 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,431.28	3,711.44	4,719.84	55.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,180.00	1,380.00	38.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,991.28	5,891.44	6,099.84	50.87
Approved Total (Overridden) (S\$)		4,700.00		

Nett Amount (S\$)	11,991.28	4,700.00	7,291.28	60.80
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 10/05/2021

Date Inspected: 10/05/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Cheong Cheong Motor Service Pte Ltd (HQ)
 Block 5032, Ang Mo Kio, Park 2, #01-293
 Singapore 569535

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR	Bent	1,289.20 FL	*1,125.80 FL
2	1		*FRONT RIGHT DOOR HINGE TOP	Repair	67.20 FL	*- FL
3	1		*FRONT RIGHT DOOR HINGE LOWER	Repair	67.20 FL	*- FL
4	1		*FRONT RIGHT DOOR INNER LOCK	Repair	423.50 FL	*- FL
5	1		*FRONT RIGHT FENDER	Buckled	580.60 FL	*580.60 FL
6	1		*FRONT RIGHT FENDER INNER SHIELD	Serviceable	130.60 FL	*- FL
7	1		*FRONT RIGHT FENDER ARCH	Repair	153.20 FL	*- FL
8	1		*REAR RIGHT DOOR	Bent	1,987.80 FL	*912.30 FL
9	1		*REAR RIGHT DOOR RUBBER	Cut	186.60 FL	*133.80 FL
10	1		*REAR RIGHT DOOR HINGE TOP	Repair	88.80 FL	*- FL
11	1		*REAR RIGHT DOOR HINGE LOWER	Repair	88.80 FL	*- FL
12	1		*REAR RIGHT DOOR INNER LOCK	Repair	262.30 FL	*- FL
13	1		*ROCKER PANEL	Bent	1,876.30 FL	*376.60 FL
14	1		*ROCKER PANEL GARNISH	Missing	1,025.20 FL	*377.50 FL
15	1		*DOOR CENTER PILLAR INNER	Repair	245.60 FL	*- FL
16	1		*DOOR CENTER PILLAR OUTER	Repair	933.50 FL	*- FL
17	1		*REAR WHEEL ARCH	Dented	172.10 FL	*172.10 FL
18	1		*REAR BUMPER SIDE RIGHT	Buckled / Cut	195.20 FL	*195.20 FL
19	1		*REAR RIGHT TYRE RIM	Dented	765.40 FL	*765.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	10,539.10	4,639.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,107.82	927.86
Total Parts (\$\$)	8,431.28	3,711.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	4 WHEEL ALIGNMENT WITH COMPUTER RE-SET	New	80.00	60.00
2	STRIP /REFIT CUSHION SEAT /CARPET & ROOF TOP CUSHION	New	480.00	120.00
3	KNOCKING PUSH OUT RIGHT SIDE ACCIDENT PARTS CUT & WELD DOOR PILLARS STRIP /REFIT ABOVE ACCESSORIES	New	1,800.00	900.00
4	SPRAY PAINT & SPRAY ANTI-TUFF-KOTE ON RIGHT SIDE ACCIDENT AFFECTED AREAS	New	1,200.00	1,100.00
Gross Labour Cost (\$)			3,560.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >