

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21005642/TGA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** FBR8622J**Insured Vehicle No :** SLU1869B

Date of Loss: 29/04/2021

Nature of Claim:

TP

Claim No: 4890388708SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBR8622J**

Make &amp; Model: YAMAHA TRICITY, 155cc ABS

Engine No: G3H3E059480

Reg. Date: 06/11/2020 (Man. Year: 2019)

Chassis No: MLESG381000059475

Colour: Grey

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 R14

Rear Tyre Size: 130/70 R13

Front Left Side: ARC 5 mm

Rear Left Side: ARC 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>              | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                              | 2,134.00          | 1,920.60          | 213.40            | 10.00         |
| Miscellaneous Items                | 0.00              | 0.00              | 0.00              |               |
| Labour                             | 670.00            | 320.00            | 350.00            | 52.24         |
| Paintwork Labour                   | 0.00              | 0.00              | 0.00              |               |
| Towing                             | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>           | <b>2,804.00</b>   | <b>2,240.60</b>   | <b>563.40</b>     | <b>20.09</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>      | 196.28            | 156.84            | 39.44             | 20.09         |
| <b>Nett Amount (S\$)</b>           | <b>3,000.28</b>   | <b>2,397.44</b>   | <b>602.84</b>     | <b>20.09</b>  |
| <b>Global Sum Settlement (S\$)</b> |                   | <b>0.00</b>       |                   |               |

INSPECTION

Date of Assignment: 10/05/2021

Date Inspected: 10/05/2021

Inspected At:

Atan Motoring Supply Pte Ltd (HQ)  
Block 3006 Ubi Road 1, #01-368/370  
Singapore 408700

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition | Repairer's | Amount     |
|-----|-----|----------|----------------------------------|-----------|------------|------------|
| 1   | 4   |          | *EMBLEM                          | Necessary | 80.00 F    | *80.00 FL  |
| 2   | 1   |          | *RIGHT BRAKE LEVER               | Broken    | 25.00 F    | *25.00 FL  |
| 3   | 1   |          | *RIGHT BALANCER                  | Cut       | 25.00 F    | *25.00 FL  |
| 4   | 1   |          | *HANDLE BAR                      | Bent      | 98.00 F    | *98.00 FL  |
| 5   | 1   |          | *SET SIDE MIRROR                 | Cut       | 58.00 F    | *58.00 FL  |
| 6   | 1   |          | *RIGHT FRONT FORK SHAFT COMPLETE | Bent      | 550.00 F   | *550.00 FL |
| 7   | 1   |          | *LEFT FORK ARM                   | Bent      | 178.00 F   | *178.00 FL |
| 8   | 1   |          | *FRONT INNER COWLING             | Cut       | 28.00 F    | *28.00 FL  |
| 9   | 1   |          | *LEFT FRONT MUDGUARD             | Cut       | 39.00 F    | *39.00 FL  |
| 10  | 1   |          | *RIGHT FRONT MUDGUARD            | Cut       | 39.00 F    | *39.00 FL  |
| 11  | 1   |          | *LEFT FRONT MUDGUARD COVER       | Cut       | 25.00 F    | *25.00 FL  |
| 12  | 1   |          | *RIGHT FRONT MUDGUARD COVER      | Cut       | 25.00 F    | *25.00 FL  |
| 13  | 1   |          | *FRONT INNER BRACKET             | Bent      | 115.00 F   | *115.00 FL |
| 14  | 1   |          | *LEFT FRONT COVER                | Cut       | 82.00 F    | *82.00 FL  |
| 15  | 1   |          | *RIGHT FRONT COVER               | Cut       | 82.00 F    | *82.00 FL  |
| 16  | 1   |          | *LEFT FRONT OUTER COVER          | Cut       | 38.00 F    | *38.00 FL  |
| 17  | 1   |          | *RIGHT FRONT OUTER COVER         | Cut       | 38.00 F    | *38.00 FL  |
| 18  | 1   |          | *RIGHT FRONT SIGNAL LIGHT        | Cut       | 42.00 F    | *42.00 FL  |
| 19  | 1   |          | *LEFT INNER COVER                | Cracked   | 32.00 F    | *32.00 FL  |
| 20  | 1   |          | *LEFT LOWER FLOORBOARD COVER     | Cracked   | 44.00 F    | *44.00 FL  |
| 21  | 1   |          | *RIGHT LOWER FLOORBOARD COVER    | Cut       | 44.00 F    | *44.00 FL  |
| 22  | 1   |          | *LEFT REAR COVER                 | Cut       | 48.00 F    | *48.00 FL  |
| 23  | 1   |          | *RIGHT REAR COVER                | Cut       | 48.00 F    | *48.00 FL  |
| 24  | 1   |          | *SEAT COVER                      | Cut       | 100.00 F   | *100.00 FL |
| 25  | 1   |          | *BELT COVER                      | Cut       | 48.00 F    | *48.00 FL  |
| 26  | 1   |          | *AIR BOX COVER                   | Cut       | 50.00 F    | *50.00 FL  |
| 27  | 1   |          | *EXHAUST PROTECTOR               | Cut       | 33.00 F    | *33.00 FL  |
| 28  | 1   |          | *REAR BOX 42L                    | Cut       | 120.00 F   | *120.00 FL |

F=Franchise part. L=ListItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>2,134.00</b> | <b>2,134.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | 0.00            | 213.40          |
| <b>Total Parts (\$\$)</b>                                 | <b>2,134.00</b> | <b>1,920.60</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars    | Lab.Type | Repairer's    | Amount        |
|---------------------------------|----------------|----------|---------------|---------------|
| <b>Labour Items</b>             |                |          |               |               |
| 1                               | BODY ALIGNMENT | New      | 200.00        | 0.00          |
| 2                               | LABOUR         | New      | 350.00        | 200.00        |
| 3                               | TOWING         | New      | 120.00        | 120.00        |
| <b>Gross Labour Cost (\$\$)</b> |                |          | <b>670.00</b> | <b>320.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >