



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12486/ TOP GUARD SECURITY MANAGEMENT Reg No/Reg Date SMT8548A / 21/07/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069606 Engine No G4FGKH755795 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/05/2021/ 10:50	QUE	261 / Edwin Caina	33136			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800 2000.00
REPLACE REAR BUMPER, REAR BOOT AND AFFECTED AREAS 2 X 400								
REPAIR REAR END PANEL								1050 1400.00
E PNT98000								80 120.00
SPRAY ON REAR BUMPER, BOOT, RR BUMPER BODY KIT & END PANEL 3 X 350								
E PNT88000								80.00
REMOVE AND INSTALL REAR PARKING ASSIST								
E PNT88000								80.00
REMOVE AND INSTALL REAR BODYKIT FOR FACILITATE REPAIR								
M SUNDRY								30.00
TO PERFORM RUST PREVENTION								
A 54900099								129.00
CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								40.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20 50.00
TO SUPPLY C&C EMBLEM								
M SUNDRY								
SUNDRIES					1.00	100.00	20.00	80.00
M W/STRIP-TRUNK LID OPNG X N/A					1.00	112.00	20.00	89.60
M LATCH ASSY-TRUNK LID X N/A					1.00	40.00	20.00	32.00
M STRIKER ASSY-TRUNK LID X N/A					1.00	1297.00	20.00	1037.60
M PANEL ASSY-TRUNK LID					1.00	28.00	20.00	22.40
M EMBLEM-CERATO REC					1.00	32.00	20.00	25.60
M ORNAMENT-KIA NO.115 REC					1.00	651.00	20.00	520.80
M COVER-RR BUMPER					1.00	241.00	20.00	192.80
M COVER-RR BUMPER LWR ? X N/A					1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP, RH CUT					1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH ? X N/A					1.00	318.00	20.00	254.40
M BEAM-RR BUMPER ? X N/A					2.00	2.00	20.00	3.20
M GROMMET ASSY-SCREW REC					7.00	1.00	20.00	5.60
M CLIP REC								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12486/ TOP GUARD SECURITY MANAGEMENT Reg No/Reg Date SMT8548A / 21/07/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069606 Engine No G4FGKH755795 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/05/2021/ 10:50	QUE	261 / Edwin Caina	33136			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	STAY-RR BUMPER LH	X	MAI		1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH	X	MAI		1.00	65.00	20.00	52.00
M	BRACKET-RR BEAM UPR MTG, LH	X	MAI		1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG, RH	X	MAI		1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR, CTR	X	MAI		1.00	6.00	20.00	4.80
R	BRACKET-RR BEAM LWR MTG	X	MAI		2.00	6.00	20.00	9.60
M	RETAINER-BUMPER SIDE MTG	X	MAI		8.00	3.00	20.00	19.20
M	BRACKET ASSY-RR BPR SIDE UPR, L	X	MAI		1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR, R	X	MAI		1.00	31.00	20.00	24.80
M	NEW K3 2020 GRAVITY BLUE B4U	X	R		1.00	1721.00	00.00	1721.00

Estimate

SURVEYOR NAME: Stere CLKK
 SURVEYOR SIGNATURE: 2/6/21, 10.30 am
 DATE: WIL PM
 REMARKS: P/P
By Bel Sky
4 days

Confirm & accepted by the repairer on the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

7% GST on **Nett** 8,261.80
 578.33
Total Payable 8,840.13

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.