



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2105777
INV Date 17/08/2021
Reference CC4/LPC21005655/Kgs3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMG 3724J
Insured Veh. SMD 9159S
Claim No. 20/21/21/VP05/024545
Policy No. Z20VP05027505
Accident Date 07/05/2021
Inspection Date 10/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC21005655/Kgs3q2

Date: 17/08/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 9159S	Veh. Inspected	SMG 3724J
Policy No.	Z20VP05027505	Coverage (\$)	0.00
Claim No.	20/21/21/VP05/024545	Excess (\$)	0.00
Assign From	GERALD	Assign Date	10/05/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	RU11305047	Colour	METALLIC PEARL WHITE
Odometer	24787 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2021	Inspection Date	10/06/2021
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 3724J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BENT	860.00	523.10
1	FRONT BUMPER RH TOW COVER	DISTORTED	70.00	70.00
1	FRONT BUMPER LOWER SPOILER	SERVICEABLE	250.00	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	37.00	37.00
1	FRONT BUMPER RH FOG LAMP COVER	SERVICEABLE	50.00	-
1	FOG LAMP RH	SERVICEABLE	189.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	175.00	-
1	RADIATOR GRILLE CHROME	SERVICEABLE	380.00	-
1	RADIATOR GRILLE BASE	DENTED / CUT	360.00	360.00
1	RADIATOR GRILLE UPP BRACKET	CRACKED	88.00	88.00
1	RADIATOR GRILLE TOP COVER	SERVICEABLE	76.00	-
1	FRONT REINFORCEMENT	BENT	392.00	321.20
1	HEAD LAMP RH	MTG CRACKED	1,684.00	1,684.00
	LESS 20% DISCOUNT		-922.20	-616.66
			3,688.80	2,466.64
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	45.00	-
			45.00	-
<u>LABOUR</u>				
	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN THE AFFECTED PARTS.		800.00	300.00
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE BUMPER SENSORS.	NOT NECESSARY	60.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		600.00	240.00
			1,690.00	560.00
GRAND TOTAL			5,423.80	3,026.64



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	-----------------

Report Ref No. CC4/LPC21005655/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3724J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3724J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3724J

RE-INSPECTION

