

MBM WHEELPOWER PTE LTD



Your Ref: SMD9159S
Our Ref: SMG3724J

To: LONPAC

CC

Fax

Not Authorised
Anthony Bepain
2-3 days

Date: 7/5/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: HONDA VEZEL 1.5
Chassis No.: RU11305047
Engine No.: L15B5555055
Year of Make: 2018
Accident Date: 7 May 2021

ESTIMATE FOR VEHICLE NO. : SMG3724J

DESCRIPTION	QTY	List Price	
FRONT BUMPER	1	\$ 860.00	✓
FRONT BUMPER RH TOW COVER	1	\$ 70.00	✓
FRONT BUMPER LOWER SPOILER	1	\$ 250.00	X
FRONT BUMPER SIDE RETAINER RH	1	\$ 37.00	✓
FRONT BUMPER RH FOG LAMP COVER	1	\$ 50.00	?
FOG LAMP RH	1	\$ 189.00	?
FRONT BUMPER LOWER GRILLE	1	\$ 175.00	X
RADIATOR GRILLE CHROME	1	\$ 380.00	X
RADIATOR GRILLE BASE	1	\$ 360.00	✓
RADIATOR GRILLE UPP BRACKET	1	\$ 88.00	?
RADIATOR GRILLE TOP COVER	1	\$ 76.00	X
FRONT REINFORCEMENT	1	\$ 392.00	?
HEAD LAMP RH	1	\$ 1,684.00	?
		Total: \$	4,611.00
		LESS 20%	(922.20)
		Parts Total: \$	3,688.80
			\$ 45.00 X
			800.00 <i>300d</i>
			150.00 X <i>nn</i>
			60.00 X <i>nn</i>
			80.00 <i>20d</i>
			600.00 <i>24d</i>
		Total: \$	5,423.80
		7% GST: \$	379.67
		Grand Total: \$	5,803.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

S/NETT:

FRONT NUMBER PLATE

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

TO APPLY ANTI RUST COATING

TO REMOVE & REPLACE BUMPER SENSORS

TO CHECK & RECONNECT ALL NECESSARY WIRING

TO SPRAY PAINT ON THE AFFECTED AREAS