



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |                               |  |
|--|---|-----------------|-------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909   |   |                 | Ref: CS3/CTI21001634/Qtf3n2-1 |  |
|  |   |                 | Date: 12/05/2021              |  |
|  |   |                 | Code: CTI                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                 |                               |  |
| Insured Veh.   | GBH 1011X                                   | Veh. Inspected  | SMH 1944Z                     |  |
| Policy No.   | DMCVSNW00126182000                          | Coverage (\$)   | 0.00                          |  |
| Claim No.  | SNM21D200574/C02                            | Excess (\$)     | 0.00                          |  |
| Assign From  | JENNY LEW                                   | Assign Date     | 10/05/2021                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |                               |  |
| Make & Model   | MAZDA 6 SEDAN                               | c.c             | 1998                          |  |
| Engine No.   | HIDDEN                                      | Year of Reg.    | 2019                          |  |
| Chassis No.  | JM6GL1072K0311710                           | Colour          | GREY                          |  |
| Odometer   | 27246 KM                                    | Steering        | IN ORDER                      |  |
| Brakes   | IN ORDER                                    | Modification    | SPORTS RIM                    |  |
| General  | FAIR  |                 |                               |  |
| <b>3. Conditions of Tyres</b>  |   |                 |                               |  |
|  | Size  | Make            | Balance                       |  |
| R/H Front Tyre   | 225/55 R17                                  | BRIDGESTONE     | 6 mm                          |  |
| L/H Front Tyre   | 225/55 R17                                  | BRIDGESTONE     | 6 mm                          |  |
| R/H Rear Tyre  | 225/55 R17                                  | BRIDGESTONE     | 6 mm                          |  |
| L/H Rear Tyre  | 225/55 R17                                  | BRIDGESTONE     | 6 mm                          |  |
| <b>4. Description of Damages</b>   |   |                 |                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                 |                               |  |
| <b>5. General Information</b>  |   |                 |                               |  |
| Accident Date  | 29/01/2021                                  | Inspection Date | 03/02/2021                    |  |
| Survey held at   | 160 SIN MING DRIVE #06-10 SIN MING AUTOCITY |                 |                               |  |
| Repairer   | LIAN HENG PAINTER CO.                       |                 |                               |  |
| <b>5a. Remarks</b>   |   |                 |                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                               |  |
| <b>5b. Estimate Days of Repair</b>   |   |                 |                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   |                 | <b>3 Working Days</b>         |  |