

CHIN HUI CAR RENTAL

REGN. NO.: 53090791K

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76, SINGAPORE 575642. TEL: 6453 4680

OFFICIAL RECEIPT

M/s MCCARL LEONARDO
BLK 314B PUNGGOL WAY
#18-623, SINGAPORE 822314.

No: 273301

Date: 06.02.2021


S/No.	Description	Amount
1	RENTAL FEES FOR SGU 6566B VRA NO. 8953	\$ 720.00

SINGAPORE DOLLARS SEVEN HUNDRED TWENTY ONLY.

PAYMENT MODE:

CASH -

CHEQUE -



Chin Hui Car Rental

CHIN HUI CAR RENTAL

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76,
SINGAPORE 575642. TEL: 6453 4680
REGN. NO.: 53090791K

VEHICLE RENTAL AGREEMENT

NO: **8953**

HIRER'S PARTICULAR		Vehicle No: 5406566B		Mileage Out: 135885km	
Hirer: <u>MCLARI LEONARDO</u>		Make & Model: <u>Toyota Camry</u>		Auto / Manual Group:	
NRIC / Passport No: <u>S88799027</u> Date of Birth: <u>23-09-1988</u>		OUT : Date <u>03/02/2021</u>		OUT : Time <u>10:30AM</u>	
Address: <u>BLK 314B PUNGGOL WAY</u>		Replace Veh No:		Mileage Out:	
<u>#18-623 S(822314)</u>		OUT : Date		OUT : Time	
Driving Licence No: <u>18 Oct 2012</u> Pass Date:					
Contact Number: <u>9 222 1631</u>					
DRIVERS PARTICULARS (if different from Hirer)		CHARGES			
Appointed Driver:		Daily <u>4</u> @ \$ <u>180/-</u> per day <u>720.00</u>			
NRIC / Passport No:		Weekly @\$ per week			
Address:		Monthly @\$ per month			
Driving Licence No:		Hours @\$ per hour			
Contact Number:		Others @\$			
		SUB-TOTAL \$ <u>720.00</u>			
		TOTAL CHARGES \$ <u>720.00</u>			
		IMPORTANT! FOR SINGAPORE USE ONLY			
		Excess Liability : \$S\$2500.00			
		Malaysia Excess (With Prior Consent) :			
		Hirer's Signature <u>[Signature]</u>			
		Addition Driver's Signature _____			
New Insurance Policy Terms & Conditions as at 08-12-2010 1. NOT PERMITTED TO DRIVE - Not Covered Driver Age 22 years old and below Driver above Age 70 years old Driver less than 2 years Driving Experience 2. ADDITIONAL EXCESS - S\$3000.00 Driver Age 23 to 25 years old with 2 years driving experience Driver Age 65 to 70 years old with 2 years driving experience					
REMARKS					
<u>SMH9442 (TP-29/1/21)</u>					
<u>(Marda6)</u>					

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CHIN HUI CAR RENTAL in connection with this agreement is true.

* IMPORTANT

- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AND ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CHIN HUI CAR RENTAL.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CHIN HUI CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	SIGNATURE OF HIRER / DRIVER
<u>06/02/21</u>	<u>2:35pm</u>	<u>136009</u>	<u>[Signature]</u>	<u>[Signature]</u>

160 SIN MING DRIVE #06-10 SIN MING AUTOCITY SINGAPORE 575722
TEL : 64535779 FAX : 64533173
Reg No : 070118/00-X

聯興噴漆公司
LIAN HENG PAINTER CO.,
160 SIN MING DRIVE, #06-10
SIN MING AUTOCITY
SINGAPORE 575722
TEL: 6453 5779 FAX: 6453 3173



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Invoice

Customer: Mccarl Leonardo
C/o: 160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722

Date: 27.02.2021

Invoice No: NS-2021-036

Description		Amount
Vehicle No:	SMH1944Z	
Make & Model:	Mazda 6 (A)	
Our reference:	AAS/2021/036	
Services rendered for appraiser / inspection report		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection Fees		
SGD Dollar : Five hundred thirty seven dollar only	Total:	SGD \$ 537.00

Notes:

All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.



Absolute Appraisal Services Pte Ltd



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Mccarl Leonardo
C/o: 160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722

Date of report: 27.02.2021
Date of request: 02.02.2021
Date of inspection: 02.02.2021
Date of accident: 29.01.2021
Claim type: Third Party Claim

Report No: AAS/2021/036

Particulars of affected vehicle:

Registration no: SMH1944Z
Make/Model: Mazda 6 (A)
Year of registration: 2019/19
Colour: Metallic Grey

Odometer: 27246 km
Engine Capacity: 1998 cc
Engine no: PE21254670
Chassis no: JM6GL1072K0311710

Condition of tires:

Front Left: 6mm
Make: Bridgestone
Rear Left: 6mm
Make: Bridgestone

Front Right: 6mm
Make: Bridgestone
Rear Right: 6mm
Make: Bridgestone

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Lian Heng Painter Company
160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 6,666.72
Revised estimate:	\$ 5,909.12
Recommended reserve:	\$ 4,750.00 (Lump sum)

Estimated normal duration of repairs : 6 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SMH1944Z

Report No: AAS/2021/036

W/O PREJUDICE

Point of impact

At the rear portion. The LHR was also affected.

General description of damages

The rear bumper, rear end panel, LH tail lamp, LHR fender, LHR door, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lian Heng Painter Company as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,909.12

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,750.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 77 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
 Mobile: 9688-0413 Fax: 6266-7596
 Email: absolute.app.svcs@gmail.com

Vehicle No: SMH1944Z

Report No: AAS/2021/036

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Rear bumper	1	Dented/Broken		\$ 1,266.60	\$ 1,266.60
2	Rear bumper reflector LH/RH	2	Refit	\$ 53.00	\$ 106.00	-
3	Rear bumper tow hook cover	2	Missing	\$ 15.90	\$ 31.80	\$ 31.80
4	Rear bumper parking sensor	2	Malfunctioned	\$ 193.90	\$ 387.80	\$ 387.80
5	Rear bumper retainer LH/RH	2	LH Cracked	\$ 41.00	\$ 82.00	\$ 41.00
6	Rear bumper reinforcement	1	Dented		\$ 583.30	\$ 583.30
7	Rear bumper support	1	Cracked		\$ 90.60	\$ 90.60
8	Rear bumper clips	8	Necessary	\$ 3.30	\$ 26.40	\$ 26.40
9	Tail lamp LH	1	Broken		\$ 762.80	\$ 762.80
10	Radar module LH	1	Dented/Cracked		\$ 1,625.20	\$ 1,625.20
11	Radar module bracket LH	1	Dented/Cracked		\$ 83.40	\$ 83.40
12	Rear end panel		Dented/Repair		-	-
13	LHR fender		Dented/Repair		-	-
14	LHR door		Grazed/Repair		-	-
Total:					\$ 5,045.90	\$ 4,898.90
-20%					\$ 1,009.18	\$ 979.78
List total:					\$ 4,036.72	\$ 3,919.12

S/N	Labour Description	Repairer's Est	Revised Est
1	To check rear wirings.	\$ 50.00	\$ 30.00
2	To remove & refit rear seat, rear luggage trimmings, etc.	\$ 100.00	\$ 60.00
3	To renew & transfer reverse sensors.	\$ 80.00	\$ 50.00
4	To conduct/check wheel alignment.	\$ 80.00	\$ 60.00
5	Rust proofing on rear affected panels..	\$ 120.00	\$ 90.00
6	To remove and renew rear damaged parts. Re-align all affected area.	\$ 1,000.00	\$ 750.00
7	To putty and respray all rear damaged parts. Touch up all affected area.	\$ 1,200.00	\$ 950.00

Labour Total: \$ 2,630.00 \$ 1,990.00

Grand Total: \$ 6,666.72 \$ 5,909.12

The final adjusted lump sum amount is \$4,750.00

Under normal circumstances, the repair should be completed within a reasonable period of 6 working days.

77 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.