

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SDU 1123P
at Workshop m/s: Zoom
of: _____
Insured: GBJ5735
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SDU 1123P Yr Regn: 29/3/21
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA1
Make: Lexus ES300H c.c 2487
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 1853 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTHB21B1602126591
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235/45 r18
R: _____

BS / DU / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: _____ Rear: _____
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 6/5/21 D.O.I. 10/5/21

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & RL & RL
The U/C / Chassis frame / Body Structure affected due to collision.

[Signature]	
N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 215k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 25 days Res.: Yes or No
Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 799A
Vehicle: IN / OUT
Date: _____ Person Contacted: 202 20k

Date / Time Action / Instruction
new car @ 250k. LIA 88615
headley 3702-20 (L81145-33F21) L81185-33F21
Barnet 2982-10, grille 1660-70 sensor 2125-80
After repair 29-6-21
8/11/21 confirmed Repair sum \$36,300 w.e. Elin
NOTE new parts replacement

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____
Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
TOTAL

Report Format :
Lump Sum / I.B.I. (\$)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

Not Approved

29 October 2021

ACCIDENT DATE : 06 May 2021
 OWNER : THOMAS BASUKI HARTONO

*date
10/5/21*

REG NO. : SDU 1123 P
 MAKE/MODEL : LEXUS ES300

** Repair sum @ 36,300
25 days.*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$S)
	<i>nett</i> EST ITEMS	
1	Front bonnet <i>Buc</i>	\$ 1,786.78 ✓
2	Front bonnet <i>deleter @301.40 Actuvall</i>	\$ 602.80 ✓
2	Front bonnet hinges <i>Soft</i>	\$ 197.80 ✓
1	Front bonnet lock <i>tu</i>	\$ 185.70 ✓
2	Front headlamps <i>one @3702.20 x 2 = 7404.40</i>	\$ 7,892.04 ✓
1	Front grille assy <i>one</i>	\$ 1,613.65 ✓
1	Front grille logo <i>one</i>	\$ 115.20 X
1	Front grille inner radar sensor <i>gvc</i>	\$ 459.90 ✓
1	Front licence plate garnish <i>dis</i>	\$ 110.00 ✓
1	Front bumper <i>dis</i>	\$ 835.60 ✓
1	Front bumper inner sponge <i>dis 287.30</i>	\$ 179.80 ✓
1	Front bumper reinforcement <i>Soft</i>	\$ 664.80 ✓
1	Front bumper inner retainer <i>dis</i>	\$ 196.40 ✓
2	Front bumper side chrome mouldings <i>one</i>	\$ 245.00 ✓
2	Front bumper side retainers <i>v/s one 81</i>	\$ 165.00 1pc
1	Front bumper top rubber seal <i>to in</i>	\$ 108.50 ✓
2	Front bumper tow hook covers <i>de</i>	\$ 145.00 ✓
4	Front bumper PDC sensors <i>shutted @311.40 x 2 = 623.60</i>	\$ 1,247.20 2pc
2	Front fenders <i>n</i>	\$ 2,064.60 X
1	Front support panel <i>Soft</i>	\$ 1,184.24 ✓
1	Front support panel too garnish <i>dis</i>	\$ 292.72 ✓
1	Front bumper LH chrome <i>one</i>	\$ 105.00 ✓
1	Air con condenser <i>70/Soft</i>	\$ 1,387.30 ✓
1	Radiator <i>n</i>	\$ 1,683.20 X
1	Front wheel rim - R/H <i>n</i>	\$ 1,691.80 X
1	Air cleaner box <i>one</i>	\$ 273.89 ✓
1	Rear windscreen moulding <i>one</i>	\$ 116.40 ✓
1	Rear boot lid <i>dis 2201.10</i>	\$ 2,596.50 ✓
2	Rear boot hinges <i>2</i>	\$ 264.16 X
2	Rear boot hinge covers <i>dis/de 80.00</i>	\$ 179.00 1pc
1	Rear boot inner trim <i>de</i>	\$ 285.20 ✓
1	Rear boot inner lock <i>Soft</i>	\$ 432.90 ✓
1	Rear boot lock catch <i>n</i>	\$ 89.20 X
1	Rear boot logo <i>one</i>	\$ 109.70 ✓
1	Rear boot outer chrome moulding <i>dis</i>	\$ 534.50 ✓
2	Rear boot reflectors <i>one</i>	\$ 1,377.50 ✓
		\$ 31,418.98

23871.18

	c/f:	\$	31,418.98
1	Rear boot rubber	7.11	241.92
1	Rear boot opening switch	1.1	225.20
1	Rear boot "LEXUS" emblem	1.1	120.83
1	Rear boot "ES300h" emblem	1.1	100.30
1	Rear boot number plate garnish	1.1	482.20
1	Rear boot top spoiler	3.0 / M/S	878.20
2	Rear taillamps	0.5 crn / M/S	1,177.20
1	Rear taillamp panel	0.5	374.40
1	Rear end panel	1.1	693.54
1	Rear end panel inner garnish	1.1	387.30
1	Rear keyless sensor (1 set)	1.1	198.50
1	Rear bumper	1.1	796.95
2	Rear bumper brackets	1.1	160.84
1	Rear bumper inner sponge	1.1	157.50
1	Rear bumper lower diffuser	1.1	382.20
1	Rear bumper lower under cover	1.1	233.30
2	Rear bumper reflectors	1.1	230.60
1	Rear bumper reinforcement	1.1	717.16
2	Rear bumper side retainers	1.1	161.00
1	Rear bumper chrome moulding set	1.1	198.20
4	Rear bumper PDC sensors	1.1	1,698.00
2	Rear number plate lamps	1.1	197.00
1	Rear reverse camera	1.1	1,218.00
1	Rear floor top board	1.1	382.01
1	Rear floor panel	1.1	1,668.20
1	Rear floor lower tools tray	1.1	298.50
1	Rear tools sponge board	1.1	398.20
1	Rear floor side panel	1.1	598.20
1	Rear exhaust silencer	1.1	1,448.60
2	Rear exhaust mountings	1.1	117.30
1	Rear exhaust chrome tail pipe	1.1	138.60
1	Centre exhaust pipe	1.1	2,596.80
2	Rear side blind spot monitor sensors	1.1	1,197.40
2	Rear side blind spot monitor sensor brackets	1.1	378.40
2	Rear fenders	1.1	2,861.00
2	Rear fender air gates	1.1	178.40
1	Rear fender inner garnish	1.1	276.60
2	Rear fender chrome mouldings	1.1	290.40
1	Rear fender inner shield	1.1	299.00
2	Rear fender inner trims	1.1	1,365.00
1	Rear door -RH	1.1	1,253.20
1	Rear battery panel sponge	1.1	325.30
1	Rear battery panel	1.1	519.50
			59,039.93
	Less 10%		5,903.99
			53,135.94

38589.04
 112
 34730.18

<u>SPECIAL NETT ITEMS</u>			
1	Front bumper clip (1 set)	RM	\$ 80.00 50
1	Front number plate with holder	BMT	\$ 50.00 40
1	Front tyre	11	\$ 500.00 X
1	Rear windscreen sealant	11	\$ 80.00 40
1	Rear boot inner trim clip (1 set)	RM	\$ 80.00 50
1	Rear bumper clip (1 set)	RM	\$ 100.00 50
1	Rear battery	11	\$ 400.00 X
			\$ 1,290.00

<u>LABOUR CHARGES</u>			
1	To check wiring and reset headlamps focusing.		\$ 80.00 } 30
2	To remove, replaced damaged lamps and check up rear wiring.		\$ 80.00
3	To remove and refit Inner garnishes.		\$ 180.00 100
4	To remove and refit rear reverse sensor.		\$ 120.00 50
5	To remove and refit rear reverse sensor.	Reptd	\$ 150.00 X
6	To transfer boot lid mechanism and wiring assembly.		\$ 80.00 60
7	To mount vehicle onto the chassis alignment bench.	11	\$ 450.00 X
8	To remove, replace air-con condenser, refill gas & conduct leakage test.		\$ 180.00 100
9	To remove and refit rear windscreen glass.		\$ 180.00 120
10	To remove, refit and replace exhaust silencer and mountings.	11	\$ 180.00 X
11	To apply undercoating.		\$ 380.00 120
12	Panel beating.		\$ 4,000.00 2800
13	To re-spray painting on the affected areas.		\$ 3,800.00 2000
			\$ 9,860.00

GRAND TOTAL :

\$ 64,285.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3473013

S.N-230

2-5300

4034013

102

36306.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	799A
Vehicle Details	
Vehicle No.:	SDU1123P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 May 2021
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H 4DR SEDAN (AUTO) EXECUTIVE
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	A25AN260748
Chassis No.:	JTHB21B1602126591
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$45,915.00
Original Registration Date:	29 Mar 2021
First Registration Date:	29 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$56,281.00 28140
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2031
PARF Rebate Amount:	\$42,210.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,001.00
COE Rebate Amount:	\$46,445.00
Total Rebate Amount:	\$88,655.00

The information contained herein is correct as at 10 May 2021

OK



ANNOUNCING Autolink Holdings Pte Ltd as sgCarMart Premium Dealer for the 3rd Consecutive Year



Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Nissan NV200 1.6A DX.



Very Low Mileage
Direct Owner StarAd

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 [VIEW OUR CARS](#)

Post an Ad Advertiser Login Ways of Selling

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

14 vehicles

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	lexus es300h	Any	Any	Any	Any	Any	Any	Available



Lexus ES Hybrid ES300h Sunroof **\$84,800** \$16,150 /yr 18-Mar-2015 2,494 cc - Luxury **Available**

Fuel Type: Petrol-Electric
Luxury Spec Is The Highest Option, Borneo Motor Unit With Full Borneo Servicing Records. Blind Spot Warning, Auto Fold Mirror, Elegant Black With Cream Leather Interior. Original Paintwork That Is Well Kept Beautifully. Absolutely 100% Accident-Free, Pristine Inside Out....

This car comes with 6-mth sgCarMart Warranty - the best protection for your car. [Learn More](#)

Shuang Hup Credit

Posted: 09-May-2021 Tags: 2015 Lexus ES, Lexus ES, Lexus, ES



Lexus ES Hybrid ES300h Sunroof **\$89,800** \$15,090 /yr 23-Oct-2015 2,494 cc 127,000 km Luxury **Available**

Fuel Type: Petrol-Electric
Borneo Motors Unit With Full Agent Service, 10 Years Hybrid Battery Warranty By Borneo Motors As Its Fully Maintained By Borneo Motors. 100% Accident Free! Elegant Silver Paintwork On Clean Black Interior, Promo 1.88% Interest Rate And Trade Ins Available, Call...

Sng Auto Pte Ltd

Posted: 09-May-2021 Tags: 2015 Lexus ES, Lexus ES, Lexus, ES



Lexus ES Hybrid ES300h Sunroof **\$188,800** \$20,430 /yr 15-Jan-2019 2,487 cc 45,600 km Luxury **Available**

Fuel Type: Petrol-Electric
1 Careful Business Owner! Comes With Nice Bidded Number Plate! 5-Years Borneo Warranty And 2 More Free Servicing To Go. Full Borneo Serviced! Head Up Display, Kick Boot Release/Close, 4 Doors With Keyless Functions. Various Bank/In-House Loan Schemes Avail Trade...

Posted: 08-May-2021 Tags: 2019 Lexus ES, Lexus ES, Lexus, ES



Lexus ES Hybrid ES300h Executive **\$131,800** \$15,270 /yr 19-Apr-2018 2,494 cc - Luxury **Available**

Fuel Type: Petrol-Electric
Facelift Model. Borneo Motors Warranty & Service Records. Elegant Gunmetal With Black Leather Interior. Shelter Parking Only. Paintwork In Excellent Condition. 100% Guarantee Accident Free, Pristine Inside Out. Flawless Condition. High Loan Available And Trade Ins Are W...

This car comes with 6-mth sgCarMart Warranty - the best protection for your car. [Learn More](#)

Shuang Hup Credit

Posted: 08-May-2021 Tags: 2018 Lexus ES, Lexus ES, Lexus, ES



Lexus Remote Key Duplicate/Repair Service

The price is dependent on car spec and key spec, for repair or replace the battery price from \$10 onwards.

More info about this product



Lexus ES Hybrid ES300h Sunroof **\$88,800** \$16,630 /yr 04-May-2015 2,494 cc - Luxury **Available**

Fuel Type: Petrol-Electric
Luxury Spec Is The Highest Option. Borneo Motor Unit. Sunroof, Blind Spot Warning, Auto Fold Mirror, Elegant Silver With Cream Leather Interior. Original Paintwork That Is Well Kept Beautifully. Absolutely 100% Accident-Free, Pristine Inside Out. Flawless Condition. High L...

This car comes with 6-mth sgCarMart Warranty - the best protection for your car. [Learn More](#)

