



Section A - Accident Details

| | |
|------------------------------------|--------------------|
| Registration Number | SHF337C |
| Case Reference Number | TAX/05/21/2016 |
| Registration Date | 12/12/2019 |
| Company Type | SMRT Taxis Pte Ltd |
| Make | TOYOTA |
| Model | PRIUS4FL |
| Name of Driver | SOH LAI KIM |
| Type of Accident | Side Swipe |
| Accident Date and Time | 7/5/2021 1:59 PM |
| Accident Reported Date and Time | 7/5/2021 4:21 PM |
| Is Surveyor Required? | Yes |
| Survey by | |
| Vehicle is Towed Back? | No |
| Towed Back Date and Time | |
| Replacement Vehicle issued? | No |
| Job Card Number | 24110862 |
| Special Instruction to ARC, if any | TP / REAR PORTION |
| Prepared Date and Time | 8/5/2021 9:55 AM |
| Chassis Number | |
| Mileage | |
| Work Shop | |
| Repair Completion Date and Time | |

Section B - Summary of Repair Estimates

| Summary of Repair Estimates | | |
|------------------------------|---|---|
| | Quotation from ARC | Adjusted by Surveyor, if applicable |
| Total Labour Cost | \$845.00 | \$200.00 |
| Total Spray Cost | \$1,476.00 | \$200.00 |
| Total Spare Part Cost | \$8,828.47 | \$864.09 |
| Total Other Cost | \$680.00 | \$30.00 |
| TOTAL COST | \$11,829.47 | \$1,294.09 (P/P) |
| Lump Sum Total | \$0.00 | \$0.00 |
| Number of Repair Days | 6.0 | 2.0 |
| Prepared / Adjusted By | Tuck Foo Kok | Taufikh (LKK) / ERGO |
| ARC / Surveyor Sign Off Date | 11/05/2021 12:20 PM | 11/05/2021 2:09 PM |
| Signature |  |  |
| Remarks | Total number of repair days = 2 days. SUP = 0 day. | Resurvey before paint , part by part. |

Section C - Quotation and Accident Invoice Details

| | | | |
|-------------------------|--------------|-----------------------|--|
| Quotation Number | QN-2105-0275 | Invoice Number | |
| Quotation Date | 20.05.2021 | Invoice Date | |
| Invoice Amount | | Prepared Date | |

Section D - Details of Repair Estimates
Part 1 - Labour Works

| Job Scope | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|--------------------------|--|
| TO REPAIR REAR PORTION | \$845.00 | \$200.00 |
| Total Labour | \$845.00 | \$200.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|---------------------------|--|
| TO RESPRAY REAR BUMPER | \$378.00 | \$200.00 |
| TO RESPRAY BUMPER BEAM | \$180.00 | \$0.00 |
| TO RESPRAY TAIL GATE | \$378.00 | \$0.00 |
| TO RESPRAY TAILGATE OUTSIDE GARNISH | \$180.00 | \$0.00 |
| TO RESPRAY REAR SPOILER | \$180.00 | \$0.00 |
| TO RESPRAY REAR PANEL | \$180.00 | \$0.00 |
| Total Spray Painting & Panel Beating | \$1,476.00 | \$200.00 |

Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--|---------------------------|--|
| TO CHECK WIRING AND SYSTEM FUNCTION | \$80.00 | \$0.00 |
| TO REMOVE AND REFIT WIRE HARDESS | \$200.00 | \$0.00 |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | \$120.00 | \$30.00 |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | \$120.00 | \$0.00 |
| TO REPLACE SUNDRY PARTS | \$100.00 | \$0.00 |
| TO WASH AND VACUUM | \$60.00 | \$0.00 |
| Total Other Costs | \$680.00 | \$30.00 |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|--------------------|----------------|---------------------|--|-----------------|------------------------|---------------------|-------------------------|---------------------------|--------------------------|
| | | 52159-47927 | COVER, RR BUMPER ASSY | 1.00 | \$485.60 | 100.00 | \$0.00 | Replace | Repair |
| | | 52161-16010 | CLIPS PIECE, FRT & RR BUMPER | 0.00 | \$4.50 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52462-47020 | PAD, RR BUMPER, RH & LH , 1 | 0.00 | \$4.00 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52462-47030 | PAD, RR BUMPER, RH & LH , 2 | 0.00 | \$4.00 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52462-47130 | PAD, RR BUMPER, RH & LH , 3 | 0.00 | \$11.00 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52191-47030 | SEAL, RR BUMPER ARM, RH & LH | 0.00 | \$11.30 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52576-47060 | RETAINER, RR BUMPER, LH | 0.00 | \$132.60 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52575-47060 | RETAINER, RR BUMPER, RH | 0.00 | \$132.60 | 0.00 | \$0.00 | Replace | Not Given |
| | | 52453-47900 | GUARD, RR BUMPER, LOWER | 1.00 | \$374.50 | 25.00 | \$280.88 | Replace | Replace |
| | | 52169-47070 | COVER, GUARD RR BUMPER LOWER | 1.00 | \$22.00 | 25.00 | \$16.50 | Replace | Replace |
| | | 52461-47070 | PAD, RR BUMPER, CTR | 3.00 | \$11.00 | 25.00 | \$24.75 | Replace | Replace |
| | | 81910-47030 | REAR BUMPER REFLECTOR ASSY, REFLEX, RH | 0.00 | \$39.00 | 0.00 | \$0.00 | Replace | Not Given |

R
X
X
X
X
X
X
X
X
✓
✓
✓
X

SMRT Accident Vehicle Repair Estimates

| | |
|---|--|
| SMRT Automotive Services Pte Ltd | |
| 60 Woodlands Industrial Park E4, Singapore 757705 | |
| FAX Number : 63685592 | |
| Estimator Telephone Number : 68662623 | |
| Accident Reporting Number : 68662672 | |

Date Generated : 20/05/2021

User ID : PohSuan

| | | | | | | | | | | |
|-------|--|----------------|---|------|-------------|------|----------|---------|-----------|---|
| | | 81920-47030 | REAR BUMPER REFLECTOR ASSY, REFLEX, LH | 0.00 | \$39.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 52023-47030 | REAR BUMPER REINFORCEMENT | 0.00 | \$332.70 | 0.00 | \$0.00 | Replace | Check | X |
| | | 58398-47050 | COVER, REAR FLOOR UNDER, RH | 0.00 | \$175.10 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 66259-47010 | COVER, REAR FLOOR UNDER CENTER | 0.00 | \$229.90 | 0.00 | \$0.00 | Replace | Check | X |
| | | 58399-47030 | COVER, REAR FLOOR UNDER, LH | 0.00 | \$241.90 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | | PIXEL STICKER | 2.00 | \$60.00 | 0.00 | \$120.00 | Replace | Replace | ✓ |
| | | 89997-30100 | ANTENNA, ELECTRICAL KEY | 0.00 | \$72.00 | 0.00 | \$0.00 | Replace | Check | X |
| | | | REVERSE SENSOR, REAR BUMPER | 0.00 | \$180.00 | 0.00 | \$0.00 | Replace | Check | X |
| | | 76801-47170-A1 | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB- | 0.00 | \$913.60 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 75403-48010 | EMBLEM SUB-ASSY REAR | 0.00 | \$47.90 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 75441-47220 | NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT | 0.00 | \$54.60 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 75442-47200 | NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT | 0.00 | \$54.60 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | | SMRT LOGO | 0.00 | \$7.80 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | | STICKER DECAL 6555 8888 | 0.00 | \$21.60 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 67005-47530 | TAIL GATE PANEL SUB-ASSY, BACK DOOR | 0.00 | \$1,147.80 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | TMKONG-TAILG | AUTO TAILGATE SYSTEM | 0.00 | \$2,520.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 76085-47916 | SPOILER SUB-ASSY, REAR | 0.00 | \$1,575.40 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 81006-47030 | LAMP SET, STOP CENTER | 0.00 | \$192.30 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 69350-47050 | TAIL GATE LOCK ASSY, BACK DOOR | 0.00 | \$467.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 69321-47010 | TAIL GATE LOCK COVER , BACK DOOR | 0.00 | \$30.20 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | 58307-47100 | END PANEL SUB-ASSY, BODY LOWER BACK | 0.00 | \$651.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | | SEALANT SIKAFLEX | 0.00 | \$37.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| Total | | | | | \$10,283.50 | | \$442.13 | | | |

| Added Spare Parts / Material Usage After Surveyor Signed off | | | | | | | | | |
|--|---------|--------------|--------------------------------|----------|---------------|--------------|------------------|-----------|----------------|
| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
| | | 52023-47030 | REAR BUMPER REINFORCEMENT | 1.00 | \$332.70 | 25.00 | \$249.53 | Replace | Replace |
| | | 66259-47010 | COVER, REAR FLOOR UNDER CENTER | 1.00 | \$229.90 | 25.00 | \$172.43 | Replace | Replace |
| Total | | | | | 562.60 | | 421.96 | | |

864.09
+ 200.00
+ 230.00
1,294.09