

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX4041B
GOI KAR PENG
NO 5 SEA BREEZE WALK

SINGAPORE 487393
TEL : FAX :
PH : 97702977
ATTN :

ESTIMATE BILL

Number : EB00005695
Date : 10/05/2021
Case No : AD00011789
Vehicle No : SGU2977A
Chassis: JF1SJ5KC5GG076956
Year of Mfr 2016
Policy No 5103982131-02
Model : SUBARU FORESTER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER - REPAIR	1.0			
2	REAR BUMPER SPOILER - REPAIR	1.0			
3	REAR FENDER RH - REPAIR	1.0			
4	REAR DOOR RH - REPAIR	1.0			
	Special Nett Price - Parts Sub Total				0.00
	Parts Total				0.00
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	700.00	0	700.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
7	ANTI-RUST COATING	1.0	100.00	0	100.00
	Labour 1 Sub Total				1,600.00
SINGAPORE DOLLARS : ONE THOUSAND SEVEN HUNDRED TWELVE AND CENTS ZERO ONLY			Less Excess		0.00
			SUBTOTAL		1,600.00
			GST 7.00%		112.00
			TOTAL		1,712.00

Date of accident : 09/05/2021 06:15 PM. Place : CARPARK OF 201D TAMPINES STREET 21

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE