

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/05/2021
TP Veh Reg No: GBG2615C

Estimate No: EST2100119
Date: 07 May 2021
Veh Reg No: SGW853B
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305005575
Reg. Date: 04/07/2007
Your Ref No: GBG2615C

Estimate Repair Cost to Vehicle No :SGW853B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	658.70	
2	1 PC BOOT LID LOGO	51.10	
3	1 PC BOOT LID "VIOS" EMBLEM	46.20	
4	1 PC REAR NUMBER PLATE GARNISH	129.80	
5	2 PCS REAR NUMBER PLATE LAMP	130.40	
6	1 PC BOOT LID KEY LOCK	98.80	
7	1 PC BOOT LID INNER LOCK	195.90	
8	1 PC BOOT LID INNER LOCK CHECKER	28.40	
9	1 PC BOOT LID INNER LOCK CABLE	68.50	
10	1 PC BOOT LID RUBBER	175.30	
11	1 PC REAR PANEL	620.10	
12	1 PC REAR PANEL TRIM	232.00	
13	1 PC REAR FENDER TRIM RH	355.90	
14	1 PC REAR FENDER TRIM LH	355.90	
15	1 PC TAIL LAMP - RH	357.20	
16	1 PC TAIL LAMP PANEL RH	168.90	
17	1 PC TAIL LAMP - LH	357.20	
18	1 PC TAIL LAMP PANEL LH	168.90	
19	1 PC SPARE TYRE PANEL	637.80	
20	1 PC SPARE TYRE PANEL COVER	114.90	
21	1 PC REAR SPARE TYRE PANEL RH SPONGE	214.10	
22	1 PC SPARE TYRE PANEL LH SPONGE	214.10	
23	1 PC REAR BUMPER	467.50	
24	2 PCS REAR BUMPER BRACKET	127.60	
25	2 PCS REAR BUMPER SIDE RETAINER	184.60	
26	2 PCS REAR BUMPER SMALL RETAINER	64.40	
27	1 PC REAR BUMPER MUDFLAP LH	65.90	
28	1 PC REAR BUMPER REFLECTOR - LH	82.80	
29	1 PC FRT BUMPER	427.30	
30	1 PC FRT BUMPER REINFORCEMENT	372.10	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/05/2021
TP Veh Reg No: GBG2615C

Estimate No: EST2100119
Date: 07 May 2021
Veh Reg No: SGW853B
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305005575
Reg. Date: 04/07/2007
Your Ref No: GBG2615C

Estimate Repair Cost to Vehicle No :SGW853B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31	2 PCS FRT BUMPER BRACKET	342.80	
32	2 PCS FRT BUMPER SIDE RETAINER	64.80	
33	1 PC FRT BUMPER TOP BRACKET	128.50	
34	1 PC FRT BUMPER GRILLE	94.80	
35	1 PC FRT SUPPORT PANEL	756.90	
36	1 PC FRT GRILLE	223.80	
37	1 PC FRT GRILLE CHROME	106.70	
38	1 PC HEADLAMP LH	525.30	
39	1 PC HEADLAMP RH	525.30	
40	1 PC AIRCON CONDENSER	982.30	
		10,923.50	
	Less 25%	<u>2,730.88</u>	8,192.74
	Special Net		
41	1 PC REAR NUMBER PLATE	50.00	
42	1 SET REAR PANEL TRIM CLIPS	40.00	
43	1 SET REAR FENDER TRIM CLIPS RH	50.00	
44	1 SET REAR FENDER TRIM CLIPS LH	50.00	
45	1 SET REVERSE SENSORS	250.00	
46	1 SET FRT BUMPER CLIPS	40.00	
47	1 SET FRT BUMPER GRILLE CLIPS	40.00	
48	1 PC FRT NUMBER PLATE	50.00	
49	1 PC FRT GRILLE EMBLEM	30.00	
		<u>600.00</u>	600.00
	Labour		
50	1 TO CHECK WIRING	50.00	
51	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
52	1 TO REMOVE AND REFIT INNER BOOT TRIM	120.00	
53	1 TO SPRAY UNDERSEAL	120.00	
54	1 (REAR) TO SPRAY PAINTING	1,400.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/05/2021
TP Veh Reg No: GBG2615C

Estimate No: EST2100119
Date: 07 May 2021
Veh Reg No: SGW853B
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305005575
Reg. Date: 04/07/2007
Your Ref No: GBG2615C

Estimate Repair Cost to Vehicle No :SGW853B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
55	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00	
56	1 TO CHECK WIRING	50.00	
57	1 TO REFILL AIRCON GAS	120.00	
58	1 TO SPRAY UNDERSEAL	100.00	
59	1 (FRONT) TO SPRAY PAINTING	1,200.00	
60	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		5.840.00	5.840.00
		Total	S\$ 14,632.74
		Add GST @ 7%	1,024.29
		Total Amount Payable	<u>S\$ 15,657.03</u>

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND SIX HUNDRED FIFTY SEVEN AND CENTS THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE