

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 06/05/2021

TP Veh Reg No: GBG2615C

Estimate No: EST2100119

Date: 07 May 2021

Veh Reg No: SGW853B

Make/Model: TOYOTA VIOS J AUTO

Chasis No: MR053HY9305005575

Reg. Date: 04/07/2007

Your Ref No: GBG2615C

Estimate Repair Cost to Vehicle No :SGW853B

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID Distorted	658.70	✓
2	1 PC BOOT LID LOGO New	51.10	✓
3	1 PC BOOT LID "VIOS" EMBLEM New	46.20	✓
4	1 PC REAR NUMBER PLATE GARNISH De band	129.80	✓
5	2 PCS REAR NUMBER PLATE LAMP New	130.40	x
6	1 PC BOOT LID KEY LOCK New	98.80	x
7	1 PC BOOT LID INNER LOCK Damaged	195.90	✓
8	1 PC BOOT LID INNER LOCK CHECKER ? Not New	28.40	x
9	1 PC BOOT LID INNER LOCK CABLE	68.50	x
10	1 PC BOOT LID RUBBER cut	175.30	✓
11	1 PC REAR PANEL Distorted	620.10	✓
12	1 PC REAR PANEL TRIM De band	232.00	✓
13	1 PC REAR FENDER TRIM RH ? Not New	355.90	x
14	1 PC REAR FENDER TRIM LH ? Not New	355.90	x
15	1 PC TAIL LAMP - RH cracked	357.20	✓
16	1 PC TAIL LAMP PANEL RH Repair	168.90	x
17	1 PC TAIL LAMP - LH cracked	357.20	✓
18	1 PC TAIL LAMP PANEL LH Repair	168.90	x
19	1 PC SPARE TYRE PANEL Repair	637.80	x
20	1 PC SPARE TYRE PANEL COVER torn	114.90	✓
21	1 PC REAR SPARE TYRE PANEL RH SPONGE ? De band	214.10	✓
22	1 PC SPARE TYRE PANEL LH SPONGE	214.10	✓
23	1 PC REAR BUMPER Distorted	467.50	✓
24	2 PCS REAR BUMPER BRACKET New	127.60	x
25	2 PCS REAR BUMPER SIDE RETAINER New	184.60	✓
26	2 PCS REAR BUMPER SMALL RETAINER New	64.40	x
27	1 PC REAR BUMPER MUDFLAP LH New	65.90	x
28	1 PC REAR BUMPER REFLECTOR - LH Missing	82.80	✓
29	1 PC FRT BUMPER De band	427.30	✓
30	1 PC FRT BUMPER REINFORCEMENT Bent	372.10	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/05/2021
TP Veh Reg No: GBG2615C

Estimate No: EST2100119
Date: 07 May 2021
Veh Reg No: SGW853B
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305005575
Reg. Date: 04/07/2007
Your Ref No: GBG2615C

Estimate Repair Cost to Vehicle No :SGW853B

Quantity	Description	List Price	Amount
		SS	SS
31	2 PCS FRT BUMPER BRACKET new LH Best	342.80	171.60
32	2 PCS FRT BUMPER SIDE RETAINER new	64.80	
33	1 PC FRT BUMPER TOP BRACKET new Behind	128.50	
34	1 PC FRT BUMPER GRILLE new	94.80	
35	1 PC FRT SUPPORT PANEL new Right	756.90	
36	1 PC FRT GRILLE new Grille	223.80	
37	1 PC FRT GRILLE CHROME new Dangle	106.70	
38	1 PC HEADLAMP LH new 3 canled	525.30	
39	1 PC HEADLAMP RH new	525.30	
40	1 PC AIRCON CONDENSER new Dented	982.30	
		10,923.50	
	Less 25%	2,730.88	8,192.74
	Special Net		
41	1 PC REAR NUMBER PLATE new New	50.00	
42	1 SET REAR PANEL TRIM CLIPS new New	40.00	
43	1 SET REAR FENDER TRIM CLIPS RH new 2 New	50.00	
44	1 SET REAR FENDER TRIM CLIPS LH new	50.00	
45	1 SET REVERSE SENSORS new Dangle	250.00	
46	1 SET FRT BUMPER CLIPS new New	40.00	
47	1 SET FRT BUMPER GRILLE CLIPS new New	40.00	
48	1 PC FRT NUMBER PLATE new Best	50.00	
49	1 PC FRT GRILLE EMBLEM new New	30.00	
		600.00	600.00
	Labour		
50	1 TO CHECK WIRING	50.00	30
51	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
52	1 TO REMOVE AND REFIT INNER BOOT TRIM	120.00	60
53	1 TO SPRAY UNDERSEAL	120.00	60
54	1 (REAR) TO SPRAY PAINTING	1,400.00	1000

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/05/2021
TP Veh Reg No: GBG2615C

Estimate No: EST2100119
Date: 07 May 2021
Veh Reg No: SGW853B
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305005575
Reg. Date: 04/07/2007
Your Ref No: GBG2615C

Estimate Repair Cost to Vehicle No :SGW853B

Quantity	Description	List Price	Amount
		SS	SS
55	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00	800
56	1 TO CHECK WIRING	50.00	30
57	1 TO REFILL AIRCON GAS	120.00	X
58	1 TO SPRAY UNDERSEAL	100.00	X
59	1 (FRONT) TO SPRAY PAINTING	1,200.00	400
60	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	400
		5,840.00	5,840.00
	Total		S\$ 14,632.74
	Add GST @ 7%		1,024.29
	Total Amount Payable		S\$ 15,657.03

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND SIX HUNDRED FIFTY SEVEN AND CENTS THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8851.90 Adrian Ly
L/s: 7K (Nett Value) h/s 07/05/21
11 Days.

7K