



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005670/Utf3n2	
			Date: 01/06/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	FBL 7278H	Veh. Inspected	SLL 6144Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101467/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	10/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA CIVIC (A)	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JHMF16309S203019	Colour	GREY
	Odometer	217555 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 ZR17	HANKOOK	6 mm
	L/H Front Tyre	225/45 ZR17	HANKOOK	6 mm
	R/H Rear Tyre	225/45 ZR17	HANKOOK	6 mm
	L/H Rear Tyre	225/45 ZR17	HANKOOK	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/05/2021	Inspection Date	10/05/2021
	Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	