

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	🔍 Find Next
---	---	----------	---	---	---	---	--------	---	---------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref: CS/SMO21005670/Utf3	
50 RAFFLES PLACE #03-03		Date: 10/05/2021	
SINGAPORE LAND TOWERSINGAPORE 048623		Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBL 7278H	Veh. Inspected	SLL 6144Z
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101467/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	10/05/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/05/2021	Inspection Date	10/05/2021
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			