

10/5/21
2/5/21 4200 5 days.



Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

The 9th Apr 2021
RICO Office Use Only

Parts -%20	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	16K

TO: SOOMPO

Vehicle No : SLL 6144 Z

Make & Model : HONDA CIVIC

DATE: 7/5/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	REAR BUMPER 721.10 913 ✓	1	\$ 847.30	\$ 847.30 ✓
2	REAR BUMPER SIDE RETAINER 17.10 N/S Cu 1/C	2	\$ 120.00	\$ 240.00 1/C ✓
3	TAIL LAMP LH 294.30 500 ✓	1	\$ 425.00	\$ 425.00 ✓
4	TAIL LAMP BOTTOM RETAINER LH 17 X	1	\$ 55.00	\$ 55.00 X ✓
5	REAR FENDER LH 12 X	1	\$ 956.00	\$ 956.00 X ✓
6	REAR FENDER INNER SHIELD LH 62.50 D/S ✓	1	\$ 179.40	\$ 179.40 ✓
7	REAR AIR VENT LH 17	1	\$ 89.60	\$ 89.60 X ✓
8	ROCKER PANEL LH 485.10 P2 ✓	1	\$ 956.00	\$ 956.00 ✓
9	REAR WINDSCREEN MOULDING 17 X	1	\$ 185.40	\$ 185.40 X ✓
10	REAR ABSORBER LH 17 X	1	\$ 417.40	\$ 417.40 X ✓
11	REAR LOWER ARM LH 17 X	1	\$ 332.40	\$ 332.40 X ✓
12	REAR CONTROL ARM LH 17 X	1	\$ 278.90	\$ 278.90 X ✓
13	REAR KNUCKLE ARM LH 17 X	1	\$ 654.00	\$ 654.00 X ✓
14	REAR WHEEL BEARING LH 17 X	1	\$ 260.40	\$ 260.40 X ✓
15	REAR DOOR LH 17 ✓	1	\$ 845.00	\$ 845.00 ✓
16	REAR DOOR BLACK STICKER LH 52.80 nec ✓	3	\$ 45.00	\$ 135.00 ✓
17	REAR DOOR OUTER MOULDING LH 17 X	1	\$ 172.30	\$ 172.30 X ✓
18	REAR DOOR PROTECTOR LH 105.60 nec ✓	1	\$ 217.00	\$ 217.00 ✓
19	REAR DOOR PROTECTOR CHROME LH 88.50 ✓	1	\$ 112.00	\$ 112.00 ✓
20	REAR DOOR INNER LOCK LH 17 X	1	\$ 458.00	\$ 458.00 X ✓
21	REAR DOOR INNER STEP GARNISH 17 X	2	\$ 154.00	\$ 308.00 X ✓
22	REAR DOOR LOCK CATCH LH 17 X	1	\$ 56.00	\$ 56.00 X ✓
23	REAR DOOR WEATHERSTRIP LH 111.00 nec ✓	1	\$ 198.00	\$ 198.00 ✓
24	REAR DOOR INNER TRIM LH 17 X	1	\$ 658.00	\$ 658.00 X ✓
25	REAR DOOR REGULATOR MOTOR LH 17 X	1	\$ 412.00	\$ 412.00 X ✓
26	REAR DOOR REGULATOR LH 17 X	1	\$ 265.30	\$ 265.30 X ✓

			Subtotal :	\$ 9,713.40
			Less 20%	\$ 1,942.68
			Parts Total :	\$ 7,770.72

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR BUMPER CLIP SET <i>rec</i>	1	\$ 50.00	\$ 50.00
2	TAIL LAMP CLIP SET <i>17X</i>	1	\$ 40.00	\$ 40.00
3	REAR DOOR INNER TRIM CLIPS <i>11X</i>	1	\$ 60.00	\$ 60.00
4	DOOR SUN VISOR <i>rec 80</i>	1	\$ 400.00	\$ 400.00
5	ROCKER PANEL SEALANT <i>11 50</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER COWLING CLIP <i>180.30</i>	1	\$ 50.00	\$ 50.00
7	REAR WINDSCREEN SEALANT <i>11X</i>	1	\$ 80.00	\$ 80.00
8	REAR WINDSCREEN INNER SEAL <i>17X</i>	1	\$ 50.00	\$ 50.00
9	SIDE CARBON SKIRT LH <i>one 600</i>	1	\$ 1,200.00	\$ 1,200.00
10	REAR RIM LH <i>Buy 450</i>	1	\$ 800.00	\$ 800.00
11	REAR TYRE LH <i>80 X</i>	1	\$ 450.00	\$ 450.00
	SPECIAL NETT			\$ 3,260.00

LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS <i>800</i>	\$ 1,800.00
TO SPRAY PAINT AFFECTED AREA <i>800</i>	\$ 1,800.00
REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING. <i>50</i>	\$ 100.00
REMOVE AND INSTALL REAR DOOR PARTS <i>60</i>	\$ 150.00
DISMENTLE AND INSTALL REAR WINDSCREEN. <i>11X</i>	\$ 200.00
DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING. <i>80</i>	\$ 350.00
REMOVE AND REFIT REAR UNDERACRRIGE <i>11X</i>	\$ 550.00
PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION. <i>20</i>	\$ 50.00
CONDUCT WATER LEAKAGE ON WELDING JOINT AREA. <i>11X</i>	\$ 60.00

	LABOUR TOTAL	\$ 5,060.00
--	---------------------	--------------------

	Total Parts Cost	\$ 11,030.72
	Total Labour Cost	\$ 5,060.00
	Total Repair Cost	\$ 16,090.72

I KK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2-2783-10 S-N-1240
 202 L-1810
 222646 5-27646
 4221