

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 25 May 2021

## **Preliminary Advice**

Insured Vehicle No	: YP5022Z		
TP Vehicle No	: SJJ7772M	Accident Date	: 07/05/2021
Make	: MAZDA 2	Assignment Date	: 10/05/2021
Date of Inspection	: 11/05/2021	Est. Duration of Repair	: 4
Inspection At	: ALFRED AUTO (HQ) BLK 5035 ANG MO KIO 3 #01-351, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,775.00
Revised Amount	:S\$	4,559.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,559.28
Lump Sum Repair	:S\$	3,600.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :