COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA88Y Date: 09.05.2021

Make : HYUNDAI Insurance: AIG

Model: IONIQ(G2) MVA: MS. LOKE YY

	.1011(02)				and secondary and an arrangement of the second
Qty	Parts Description / Labou	ır	Туре	Unit Price	Amount
	1 REAR BUMPER COVER				\$459.40
	10 REAR BUMPER CLIPS				\$22.00
	1 REAR BUMPER CENTRE MOULDING ASSY				\$451.25
	1 REAR BUMPER REINFORCEMENT				\$394.80
	1 REAR BUMPER REINFORCEMENT BRACKE	T RH			\$138.10
	1 REAR BUMPER FOG LAMP				\$201.50
	1 LICENCE LAMP				\$85.30
	1 ANTENNA ASSY – SMARTK				\$40.50
	1 BOOTLID HYUNDAI PLATE				\$24.30
	1 EMBLEM HYBRID				\$24.30
	1 EMBLEM – IONIQ				\$31.30
		SUB TOTAL			\$1,872.75
		LESS 20%			\$374.55
	DIS	SCOUNTED TOTAL			\$1,498.20
	1 BOOTLID COMFORT TEL NO STICKER				\$35.00
	1 BOOTLID COMFORT LOGO STICKER				\$30.00
	1 REAR NUMBER PLATE + TRIM COVER	LKK Auto Con	sultants hence n	olify	\$45.00
	1 BOOTLID COMFORT APP STICKER	the Repairer of To resurvey belo	the following:		\$30.00
	1 REAR BUMPER REVERSE SENSOR	Parts prices are	ped part(s) during ne	survey	\$180.00
		Third party surve No illegal modific	y is on a "Without Pre ation(s) is allowed	sjudice" basis	\$285.00
	Labour Charge	a socient to trigg (m(s) must be resure approval from insura	reyed and noe Company	
	PANEL BEATING	Acknowledged by R Signature:	spairer	1	\$800.00
	SPRAY PAINTING CHARGE	Date:			\$600.00
	WIRING CHARGE				\$ 50.00
	REMOVE/REFIX REVERSE SENSOR				\$80.00
		TOTAL LABOUR			\$1,530.00
		ESTIMATE TOTAL			\$3,313.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ UKK
1015/2021 1445
PIP
30 ADS
CHECK ITEM PHOTOS
AT BY PAINT PHOTOS