

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

JH MGK5850H X20108

NURUL INSYIRA BINTE MUHAMMAD RAZALI  
BLK 114 BUKIT BATOK WEST AVENUE 6  
#02-194  
S 650114

TPAIG.  
Xiao Tony

Vehicle No : SLJ 7946 E  
Make/Model : HONDA JAZZ  
Accident date : 04.05.2021

| No                | DESCRIPTION                                            | Qty | Amount (\$S)           |
|-------------------|--------------------------------------------------------|-----|------------------------|
| <b>List Items</b> |                                                        |     |                        |
| 1                 | Rear bumper <i>behind</i>                              | 1   | \$ 740.00 <i>558.</i>  |
| 2                 | Rear bumper side holder @ \$36.00 <i>RH Dmgd</i>       | 2   | \$ 72.00 <i>36.</i>    |
| 3                 | Rear bumper lower side garnish @ \$54.00 <i>RH int</i> | 2   | \$ 108.00 <i>54</i>    |
| 4                 | Rear lamp <i>at</i>                                    | 1   | \$ 336.00 <i>✓ 32</i>  |
| 5                 | Rear RH fender <i>Distorted</i>                        | 1   | \$ 855.80 <i>✓</i>     |
| 6                 | Rear RH fender inner trim <i>behind</i>                | 1   | \$ 253.50 <i>✓</i>     |
| 7                 | Rear RH fender inner shield <i>torn</i>                | 1   | \$ 240.00 <i>83.70</i> |
| 8                 | Rear RH fender lower garnish <i>new</i>                | 1   | \$ 127.50 <i>x</i>     |
| 9                 | Rear RH fender lower airvent <i>behind</i>             | 1   | \$ 48.00 <i>✓</i>      |
| 10                | Rear exhaust pipe <i>new</i>                           | 1   | \$ 630.00 <i>x</i>     |
|                   |                                                        |     | \$ 3410.80             |
| Less 20% Disc     |                                                        |     | \$ 682.16              |
| Total             |                                                        |     | \$ 2728.64             |

### Special Nett Items

|       |                                                          |   |                       |
|-------|----------------------------------------------------------|---|-----------------------|
| 1     | Rear bumper reverse sensor @ \$180.00 <i>1 piece dmd</i> | 4 | \$ 720.00 <i>180.</i> |
| 2     | Rear bumper clips (1 set) <i>new</i>                     | 1 | \$ 60.00 <i>30.</i>   |
| Total |                                                          |   | \$ 780.00             |

### Labour Cost

|       |                                                     |                        |
|-------|-----------------------------------------------------|------------------------|
| 1     | To supply rear end panel inner sealant              | \$ 200.00 <i>x</i>     |
| 2     | Remove & reinstall quarter glass                    | \$ 100.00 <i>60.</i>   |
| 3     | Remove & reinstall <i>upholstery</i>                | \$ 150.00 <i>60.</i>   |
| 4     | Remove & reinstall reverse sensor                   | \$ 150.00 <i>50</i>    |
| 5     | Remove & reinstall exhaust pipe                     | \$ 100.00 <i>x</i>     |
| 6     | Remove ,replace & repair consistent to the accident | \$ 1500.00 <i>700</i>  |
| 7     | Respray painting                                    | \$ 1300.00 <i>600.</i> |
| 8     | Tuff kote                                           | \$ 100.00 <i>60.</i>   |
| Total |                                                     | \$ 3600.00             |

Grand Total \$ 7108.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Wheel: 3520  
L/S: 2.8K  
Center offer: 2.8K ✓  
04 Days