



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**MITSUBISHI**  
**MOTORS**

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN LAY CHEO Reg No/Reg Date SME5919L / 08/10/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003683 Engine No 3A92UHH5805 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/05/2021/ 13:47	BLE	261 / Edwin Caina	10891
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FRT <sup>l</sup> BUMPER , BODY KIT , RHF <sup>l</sup> FENDER & SUPPORT PNL	1-5 X 450			675 2760.00
	REPAIR RHF DOOR & BONNET				
E PNT98000	RESPRAY FRT <sup>l</sup> BUMPER , FRT BUMPER <sup>l</sup> BODY KIT , FRT SUPPORT , RHF <sup>l</sup> FENDER ,	3 X 350			1050 2100.00
	RHF DOOR & BONNET				
E PNT88000	REMOVE & REFIT AC COND & RADIATOR				? 100.00
M SUNDRY	TOP UP AIRCON GAS				? 80.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00
	USING HI-SCAN PRO TEST				
M SUNDRY	SUPPLY FRT NUMBER PLATE WITH CASING				X 50.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				? 40.00
M SUNDRY	SUPPLY BODY PNL SEALANT				X 60.00
M SUNDRY	Sundries				20.00
M	FACE,FR BUMPER / BR / CRU	1.00	706.00	23.00	543.62
M	COVER,FR BUMPER	1.00	13.00	23.00	10.01
M	GRILLE,FR UNDER	1.00	165.00	23.00	127.05
M	BRACKET,FR BUMPER,LH X	1.00	13.00	23.00	10.01
M	BRACKET,FR BUMPER,RH / BR	1.00	13.00	23.00	10.01
M	GARNISH,FR BUMPER,LH X	1.00	127.00	23.00	97.79
M	GARNISH,FR BUMPER,RH / CUT	1.00	127.00	23.00	97.79
M	CLIP,FR BUMPER / pec	5.00	4.00	23.00	15.40
M	MARK,THREE-DJA	1.00	70.00	23.00	53.90
M	GRILLE,RADIATOR	1.00	557.00	23.00	428.89

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN LAY CHEO Reg No/Reg Date SME5919L / 08/10/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003683 Engine No 3A92UHH5805 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/05/2021/ 13:47	BLE	261 / Edwin Caina	10891
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FENDER,FR RH	✓ BU	1.00	500.00	23.00	385.00
M SHIELD,FR WHEELHOUSE,RH	✓ TN	1.00	98.00	23.00	75.46
M CLIP,INNERSHIELD	✓ MC	6.00	4.00	23.00	18.48
M PANEL ASSY,FR END	?	1.00	1055.00	23.00	812.35
M COVER,ENG ROOM UNDER,FR	X	1.00	99.00	23.00	76.23
M PANEL,AIR GUIDE,RH	?	1.00	11.00	23.00	8.47
M HEADLAMP ASSY,RH	✓ BR	1.00	663.00	23.00	510.51
M LAMP ASSY,FOG,FR LH	?	1.00	305.00	23.00	234.85
M TANK,WINDSHIELD WASHER	✓ CRU	1.00	75.00	23.00	57.75
M PANEL,AIR GUIDE	?	1.00	112.00	23.00	86.24
M RADIATOR ASSY	X	1.00	972.00	23.00	748.44
M EMBLEM ECO	✓ MC	1.00	17.00	00.00	17.00
M UNPAINTED BODYKITS	✓ BR	1.00	1643.00	20.00	1314.40
M LLC 4L	X	1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve (LKK) 10/5/21, 1:30pm  
 SURVEYOR SIGNATURE: OO- NM AL  
 DATE: Exross - ?  
 REMARKS: P/P  
M/BOL SKA  
4 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Confirm & accepted by subject to confirmation
- Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

Nett 11,119.67  
 7% GST on 11119.67 778.38  
**Total Payable 11,898.05**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.