



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV06424/Han Weili Wendy Reg No/Reg Date SKG235Y / 21/11/201 Date In/Mileage 08/05/2021/ 0 Chassis No JMFXTGA2WJZ000945 Engine No 4B11TR9560 Make/Model MIT/ASX 2.0 CVT 2WD (N06) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	08/05/2021/ 11:07	QUK	289 / Patrick Lee / Kevin	10868		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT ¹ BUMPER, BONNET & AFFECTED AREAS REPAIR ON FRT RH FENDER				1-5 X 450			675 1800.00
E PNT98000 SPRAY ON FRT ¹ BUMPER, HOOD & FRT RH ¹ FENDER				3 X 350			1050.00
M SUNDRY PERFORM RUST PREVENTION							40 80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREAS							240.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME				CUT			50.00
M SUNDRY SUNDRIES							20 50.00
M HEADLAMP ASSY, RH				1.00	828.00	23.00	637.56
M REINFORCEMENT, FR BUMPER				1.00	53.00	23.00	40.81
M FACE, FR BUMPER				1.00	818.00	23.00	629.86
M GRILLE, FR BUMPER				1.00	206.00	23.00	158.62
M GARNISH, FR BUMPER, RH				1.00	27.00	23.00	20.79
M EXTENSION, FR BUMPER				1.00	192.00	23.00	147.84
M GRILLE ASSY, RADIATOR				1.00	344.00	23.00	264.88
M GARNISH, FR BUMPER SIDE				1.00	123.00	23.00	94.71
M GARNISH, FR BUMPER SIDE				1.00	123.00	23.00	94.71
M COVER, FR BUMPER, RH				1.00	37.00	23.00	28.49
M GARNISH, FR BUMPER SIDE				1.00	77.00	23.00	59.29
M GARNISH, FR BUMPER SIDE				1.00	77.00	23.00	59.29
M COVER, FR BUMPER				1.00	308.00	23.00	237.16
M GROMMET, FUEL FILLER LID PA				5.00	2.00	23.00	7.70
M HOOD				1.00	822.00	23.00	632.94

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV06424/Han Weili Wendy Reg No/Reg Date SKG235Y / 21/11/201 Date In/Mileage 08/05/2021/ 0 Chassis No JMFXTGA2WJZ000945 Engine No 4B11TR9560 Make/Model MIT/ASX 2.0 CVT 2WD (N06) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/05/2021/ 11:07	QUK	289 / Patrick Lee	10868

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M MOULDING,FR WHEEL ARCH,RH ?	1.00	132.00	23.00	101.64
M FENDER,FR RH X R	1.00	512.00	23.00	394.24

Estimate

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 10/5/21, 1.00p

DATE: 00-AL AL

REMARKS: Excess - ?

P/P, My Bel say
4 days

Confirm & accepted by LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
Authorized signatory and company stamp

7% GST on **Nett** 7,030.53
7030.53 492.14
Total Payable 7,522.67

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.