

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV06424/Han Weili Wendy Reg No/Reg Date SKG235Y / 21/11/201 Date In/Mileage 08/05/2021/ 0 Chassis No JMFXTGA2WJZ000945 Engine No 4B11TR9560 Make/Model MIT/ASX 2.0 CVT 2WD (N06) Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	08/05/2021/ 11:07	QUK	289 / Patrick Lee	10868		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1800.00
REPLACE FRT BUMPER, BONNET & AFFECTED AREAS							
REPAIR ON FRT RH FENDER							
E PNT98000							1050.00
SPRAY ON FRT BUMPER, HOOD & FRT RH FENDER							
M SUNDRY							80.00
PERFORM RUST PREVENTION							
A 54900099							30.00
CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							240.00
TO APPLY ZERTONA COATING ON AFFECTED AREAS							
M SUNDRY							50.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME							
M SUNDRY							50.00
SUNDRIES							
M	HEADLAMP ASSY,RH			1.00	828.00	23.00	637.56
M	REINFORCEMENT,FR BUMPER			1.00	53.00	23.00	40.81
M	FACE,FR BUMPER			1.00	818.00	23.00	629.86
M	GRILLE,FR BUMPER			1.00	206.00	23.00	158.62
M	GARNISH,FR BUMPER,RH			1.00	27.00	23.00	20.79
M	EXTENSION,FR BUMPER			1.00	192.00	23.00	147.84
M	GRILLE ASSY,RADIATOR			1.00	344.00	23.00	264.88
M	GARNISH,FR BUMPER SIDE			1.00	123.00	23.00	94.71
M	GARNISH,FR BUMPER SIDE			1.00	123.00	23.00	94.71
M	COVER,FR BUMPER,RH			1.00	37.00	23.00	28.49
M	GARNISH,FR BUMPER SIDE			1.00	77.00	23.00	59.29
M	GARNISH,FR BUMPER SIDE			1.00	77.00	23.00	59.29
M	COVER,FR BUMPER			1.00	308.00	23.00	237.16
M	GROMMET,FUEL FILLER LID PA			5.00	2.00	23.00	7.70
M	HOOD			1.00	822.00	23.00	632.94

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV06424/Han Weili Wendy Reg No/Reg Date SKG235Y / 21/11/201 Date In/Mileage 08/05/2021/ 0 Chassis No JMFXTGA2WJZ000945 Engine No 4B11TR9560 Make/Model MIT/ASX 2.0 CVT 2WD (N06) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/05/2021/ 11:07	QUK	289 / Patrick Lee	10868
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MOULDING,FR WHEEL ARCH,RH		1.00	132.00	23.00	101.64
M FENDER,FR RH		1.00	512.00	23.00	394.24

Estimate

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

	Nett	7,030.53
7% GST on	7030.53	492.14
Total Payable		7,522.67

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.