



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

TPAIG.

Xiao Chan.

DATE: 08/06/2021 OUR REF: UAPL1455
REPAIR ESTIMATE YOUR BMW 730I NO: SKZ777A

WBA7E020306913501

1 FRONT BUMPER FACE <i>torn</i>	\$ 2,000.00 <i>1950</i>
2 FRONT BUMPER SENSOR ASSY <i>3x new</i>	\$ 742.00 <i>x</i>
1 FRONT R/H BUMPER SIDE RETAINER	\$ 89.00 <i>x</i>
1 FRONT R/H BUMPER FOG LAMP COVER GARNISH <i>new</i>	\$ 278.00 <i>x</i>
1 FRONT R/H HEADLAMP ASSY <i>lt</i>	\$ 6,300.00 <i>5947.</i>
1 FRONT R/H HEADLAMP LOWER GARNISH <i>new</i>	\$ 233.00 <i>x</i>
1 FRONT R/H FENDER ASSY <i>Rep</i>	\$ 1,350.00 <i>x</i>
1 FRONT R/H FENDER INNER SHIELD <i>3x new</i>	\$ 242.00 <i>x</i>
10 FRONT R/H FENDER INNER SHIELD CLIPS <i>7897</i>	\$ 50.00 <i>x</i>
	\$ 11,284.00
LESS 10% <i>7107.30</i>	\$ 1,128.40
	\$ 10,155.60

LABOUR CHARGES:-

TO DISM/REWIRE FRONT DAMAGED PORTION	\$ 200.00 <i>30.</i>
TO RESET ECU AFTER REPAIR	\$ 120.00 <i>x</i>
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$ 1,000.00 <i>200</i>
TO SEND VEHICLE FOR WHEEL ALIGHTMENT	\$ 120.00 <i>x</i>
TO PUTTY AND RESPRAY DAMAGED PORTION <i>430</i>	\$ 1,000.00 <i>200</i>
TO SPARY UNDERCOATING IN REPAIR	\$ 80.00 <i>x</i>
	\$ 12,675.60

total: 7537.30

L/S: 6K.

0 3 Days.

6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: