

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Make Jashin
Not Authorized
Make
10/5/21
2/s \$ 4300/
4 days.

VEHICLE No: SLU 2101B

1PC	BOOTLID	Bent/3uc	1245.10	\$1,485.10	
1PC	BOOTLID REAR LOGO	nee	68.10	\$86.60	
1PC	BOOTLID CAMRY EMBLEM	nee	62.20	\$88.50	
2PCS	BOOTLID REFLECTORS @\$555.10	11		\$1,110.20	X
1PC	BOOTLID OUTER GARNISH	R		\$645.10	X
1PC	BOOTLID INNER LOCK	7w1	409.10	\$509.00	
1PC	BOOTLID INNER TRIM	11		\$566.00	X
1PC	BOOTLID WEATHERSTRIP	7w1		\$399.10	
1PC	BOOTLID 2.4 EMBLEM	nee	266.20	\$60.00	
1PC	REAR BUMPER	De	40.80	\$845.00	
2PCS	REAR BUMPER RETAINERS @\$ 65.10	3uc	566.10	\$130.20	X
1PC	REAR BUMPER REINFORCEMENT	DD	392.20	\$599.00	
1SET	REAR BUMPER CLIPS	nee		\$50.00	
2PCS	REAR BUMPER REFLECTORS @\$85.10	11		\$170.20	X
1PC	REAR END PANEL	DD		\$799.00	
1PC	REAR END PANEL TOP GARNISH	7w1	605.10	\$499.00	
2PCS	TAILLAMPS @\$845.10	8uc	355.10	\$1,690.20	X
2PCS	TAILLAMP HOUSING PANELS @\$485.10	11		\$970.20	X
1PC	REAR FLOOR PANEL	11		\$1,145.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11	382.30	\$620.00	
				\$12,467.40	

1SET	REAR BUMPER REVERSE SENSOR	shorted	\$280.00	200
1PC	REAR END PANEL SEALANT	nee	\$50.00	
1SET	REAR FLOOR PANEL INSULATOR	11	\$300	X
1PC	REAR LICENCE PLATE W/HOLDER	11	\$50.00	X

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$100	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$100.00	60
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	950
	\$16,727.40	

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

P-4442-30
25%
P-3331-72
S-N-250
R-1820