

REPAIR DETAILS

SJJ3116J
TP/CHINA

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2021)

Parts: 144 HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJJ3116J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT RH SIDE MIRROR	0.00	0.00	*250.00 F
2	1		*1 PC FRT RH SIDE MIRROR COVER	0.00	0.00	*30.00 F
Total Parts (S\$)						280.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX FRT RH SIDE MIRROR & CHECK SYSTEM	New	50.00
2	PUTTY & RESPRAY ON THE SIDE MIRROR COVER	New	100.00
Gross Labour Cost (S\$)			150.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not within
Penny B&pain
1 day
839d

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: