

ASS. REG. BY:

REF:

C72/ 21003681/Kqf3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

CO/TP/WS/TP RES/OO RES/EVA/INV/INV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No: SNM21D202674/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lump Sum: 1.21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

STJ 3116J

Yr Regn:

09.08

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

c.c

1339

Colour

n. Black

AC:

Insured / Std / NI / NA

Sp. Reading

176475

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GEB

1087333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRIm / STD A/RIm or

Tyre Size:

P:

195/55R15

R: Yokco

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

29/4/21

D.O.I.

30/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR old door mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

01/09/21 @ 11.56am revised to Tan Kah Leong via Merimen.

Kenneth confirmed final fig \$390, 1 day (Red \$40, 9%)
(No Lump Sum)

Date/Time, File Pass to?

☐

: Prell. Report

1) 15/09 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

1

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS - SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :


MER-TP

Lump Sum / I.B.I. (\$

390

Estimate Report

Page 1 of 2

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 762761

Tel: 67556142 Fax: 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (YM8923U)
Policy No:		Date of Loss:	29/04/2021
Vehicle Reg. No.:	SJJ3116J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YEO WEI JIE SHERMAN	Driver (Insured):	KHAIRUDDIN BIN ABDUL RASHID

Make/Model:	HONDA FIT, 1.3 G (A)	Vehicle Reg. Date:	08/09/2008
Vehicle Colour:	BLACK		
Engine No:	L13A4097102	Chassis No:	GE61087333
Odometer:	0 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 0

*Not Authorised
Returning B&P claim
1 day*

Description of Accident/Loss: REFER TO GIA REPORT ATTACHED.

Remarks: VEHICLE CURRENT LYING WOODLANDS WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	280.00
Miscellaneous Items	0.00
Labour	150.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	430.00
+ GST 7.00% (\$\$)	30.10
Nett Amount (\$\$)	460.10

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

<https://singapore.merlmen.com/claims/index.cfm?fusebox=MTRrepairer&fuseaction=>

REPAIR DETAILS

SJJ3116J
TP/CHINA

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2021)
 Parts: 144 HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJJ3116J)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT RH SIDE MIRROR	0.00	0.00	*250.00F
2	1		*1 PC FRT RH SIDE MIRROR COVER	0.00	0.00	*30.00F
Total Parts (S\$)						280.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX FRT RH SIDE MIRROR & CHECK SYSTEM	New	50.00
2	PUTTY & RESPRAY ON THE SIDE MIRROR COVER	New	100.00
Gross Labour Cost (S\$)			150.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not within
 Putty & Blending
 1 day

**LKK Auto Consultants hence notify
 the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/04/2021 18:49 (SGT)
Date of Accident 29/04/2021 17:08 (SGT)
Exact Location of Accident Singapore
Additional Location Information YISHUN AVE 5
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJJ3116J
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner NG LEE LEE ANGELA
NRIC No SXXXX165C
Email Address shermanywj@gmail.com
Mobile Phone No (Phone) +65-96235905
Alternative Phone No +65-96235905

VEHICLE PARTICULARS

Manufacturer Honda
Model FIT 1.3G A
Variant
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1330


INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5096398010-03
Cover Note Number 08/09/2020 -07/09/2021

DRIVER

Name of Driver YEO WEI JIE, SHERMAN
NRIC No SXXXX409D

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 5.07pm to 5.08pm, I was in vehicle SJJ 8116T going straight from Yishun Ave 5 towards Yishun Central. I was on lane 3.

Lorry YM8923U proceeded to make an illegal lane cutting from lane 2 to lane 3. He fail to observe safety and proper judgement. I turned and jam brake.

The back of lorry YM8923U scrapped my mirror. I have video evidence that captured what happen.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Speedy
NRIC/FIN No.: Chh

() Claim Own Policy (☒) Claim Thrd Party () Reporting Only
() Claim OD/TP at other workshop ()