

Lee / Mr Admin

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KWONG LAI SEE
2 FLORA DRIVE #02-15
SINGAPORE 507025

Te Ching

Denise

Contact : 90690133, 81579118

ESTIMATE

Repair Code : CLM15240

Date in : 08/05/2021

Vehicle Num. : SJM6183D

Model : SUZUKI SWIFT 1.5 MT ABS D/AIRBAG 2WD

Chassis/Eng# : JSAEZC21S00419896/M15A1327724

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER Deformed	1	607.20	✓ 607.20
REAR BUMPER BRACKET L/R Dented	2	36.70	✓ 73.40
REAR BUMPER SIDE RETAINER L/R M	2	23.10	✓ 46.20
REAR END PANEL Dented	1	316.70	✓ 316.70
REAR END PANEL AIR VENT Deformed	1	29.60	✓ 29.60
REAR END PANEL INNER TOP GARNISH Deformed	1	91.00	✓ 91.00
REAR NUMBER PLATE LAMP L/R Not new	2	30.20	X 60.40
REAR TAILGATE Repair	1	690.25	X 690.25
REAR TAILGATE 'LOGO' EMBLEM 3 New	1	48.00	✓ 48.00
REAR TAILGATE 'SWIFT' EMBLEM	1	26.10	✓ 26.10
REAR TAILGATE LOCK New	1	150.05	X 150.05
REAR TAILGATE OUTER HANDLE GARNISH 3 New	1	57.45	X 57.45
REAR TAILGATE RUBBER GUIDE STOPPER	2	9.80	X 19.60
REAR TAILGATE WEATHER STRIP SEAL New	1	96.65	X 96.65
REAR TAILLAMP L/R cracked	2	336.43	490 672.86

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

KWONG LAI SEE

2 FLORA DRIVE #02-15

SINGAPORE 507025

Contact : 90690133, 81579118

ESTIMATE

Repair Code : CLM15240

Date in : 08/05/2021

Vehicle Num. : SJM6183D

Model : SUZUKI SWIFT 1.5 MT ABS D/AIRBAG 2WD

Chassis/Eng# : JSAEZC21S00419896/M15A1327724

Subtotal before discount		1728.20	2,985.46
Percentage discount	15%	1468.97	447.82
Sub-total 1			2,537.64
REAR BUMPER CLIPS - SET	1	50.00	30 50.00
REAR BUMPER LOWER SPOILER	1	800.00	750 800.00
REAR BUMPER REVERSE SENSOR - SET	1	250.00	20 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	10 30.00
REAR EXHAUST SILENCER BOX	1	1500.00	1300 1,500.00
REAR EXHAUST SILENCER GASKET	1	60.00	30 60.00
REAR EXHAUST SILENCER RUBBER MOUNTING	2	40.00	X 80.00
REAR NUMBER PLATE	1	25.00	✓ 25.00
REAR NUMBER PLATE HOLDER	1	50.00	30 50.00
REAR REVERSE CAMERA	1	700.00	X 700.00 - 450
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	40.00	X 40.00
REAR TAILGATE WINDSCREEN GLASS SEALANT	1	60.00	X 60.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	20 40.00
Subtotal before discount			3,685.00
Percentage discount	0%		0.00
Sub-total 2			3,685.00
Parts-total			6,222.64

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KWONG LAI SEE
2 FLORA DRIVE #02-15
SINGAPORE 507025

Contact : 90690133, 81579118

ESTIMATE

Repair Code : CLM15240

Date in : 08/05/2021

Vehicle Num. : SJM6183D

Model : SUZUKI SWIFT 1.5 MT ABS D/AIRBAG 2WD

Chassis/Eng# : JSAEZC21S00419896/M15A1327724

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

✓ 60.00

To remove, reinstall tailgate windscreen

X 150.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 120.00

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

800 1,400.00

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

60 150.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1690 650 1,200.00

To apply anti-rust chemical on repaired and replaced panel.

60 80.00

Labour Total

3,160.00

Parts & Labour Total

9,382.64

total: 6003.97

2/5 4.8K

05 Days

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4.8K