



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13229/LUI WEI MIN, CHARMAINE Reg No/Reg Date SMW694Y / 30/10/202 Date In/Mileage 17/05/2021/ 0 Chassis No KNAF5416ML5057703 Engine No G4FGKH751115 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/05/2021/ 14:28	QUK	282 / Kevin Leong	33217

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER AND AFFECTED AREAS				400 800.00
E PNT98000 SPRAY ON FRT BUMPER				350.00
M SUNDRY TO SUPPLY FRT LICENSE PLATE WITH FRAME - BT				50.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				20 30.00
M GRILLE ASSY-RADIATOR - BR	1.00	328.00	20.00	262.40
M COVER-FR BUMPER - BR	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER - XMM	1.00	262.00	20.00	209.60
M ABSORBER-FRONT BUMPER ENERGY - BR	1.00	84.00	20.00	67.20
M BEAM COMPLETE-FR BUMPER - XMM	1.00	497.00	20.00	397.60
M ORNAMENT-KIA NO.115 - REC	1.00	32.00	20.00	25.60

Estimate

Steve CLKK) 17/5/21, 11.45 am
 OO- M1 PL
 EXCISE - ?
 P/P
 By Bel sy
 3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by	7% GST on	2,848.80	199.42
	Nett	2,848.80	
	Total Payable		3,048.22

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.