



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV13229/LUI WEI MIN, CHARMAINE
	Reg No/Reg Date	SMW694Y / 30/10/202
	Date In/Mileage	17/05/2021/ 0
	Chassis No	KNAF5416ML5057703
	Engine No	G4FGKH751115
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/05/2021/ 14:28	QUK	282 / Kevin Leong	33217
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 REPLACE FRT BUMPER AND AFFECTED AREAS				800.00	
E PNT98000 SPRAY ON FRT BUMPER				350.00	
M SUNDRY TO SUPPLY FRT LICENSE PLATE WITH FRAME				50.00	
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				30.00	
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00	
M SUNDRY SUNDRIES				30.00	
M GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40	
M COVER-FR BUMPER	1.00	633.00	20.00	506.40	
M GRILLE-FRONT BUMPER	1.00	262.00	20.00	209.60	
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20	
M BEAM COMPLETE-FR BUMPER	1.00	497.00	20.00	397.60	
M ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60	

Estimate

Confirm & accepted by

	Nett	2,848.80
7% GST on	2848.80	199.42
Total Payable		3,048.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.