

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Koh Ming Shao

Date: 15 Jun 2021

**Preliminary Advice**

|                    |                                                                                                |                         |              |
|--------------------|------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLQ9822D                                                                                     | Accident Date           | : 09/05/2021 |
| TP Vehicle No      | : SLG2051K                                                                                     | Assignment Date         | : 10/05/2021 |
| Make               | : HONDA SHUTTLE                                                                                | Est. Duration of Repair | : 3          |
| Date of Inspection | : 11/05/2021                                                                                   |                         |              |
| Inspection At      | : SM AUTOMOTIVE - KAKI BUKIT (HQ)<br>BLOCK C - 1, KAKI BUKIT AVE 6, #01-43<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,897.96 |
| Revised Amount              | :S\$ | 2,033.04 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 2,033.04 |

|                 |      |          |
|-----------------|------|----------|
| Lump Sum Repair | :S\$ | 1,600.00 |
|-----------------|------|----------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( x ) Lump Sum repair
  
- ( x ) The above survey was conducted on a 'without prejudice' basis.