

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 09/05/2021

Estimated repair cost for vehicle no: SLG2051K HONDA SHUTTLE 1.5G A

CHASSIS: GK81004574 (2016)

10/05/2021

TP MS16.
Hui zhen.

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Deled.</i>	\$1,189.00	\$1,189.00 ✓
2	2	REAR BUMPER SPONGE <i>ambd LH</i>	\$59.00	<i>59</i> \$118.00 ✓
3	2	REAR BUMPER SIDE RETAINER <i>LH Rnd</i>	\$85.00	<i>145</i> \$170.00 <i>85</i>
4	1	REAR BUMPER REFLECTOR LH <i>ambd</i>	\$121.00	<i>45.30</i> \$121.00 ✓
5	1	REAR BUMPER REFLECTOR OUTER GARNISH LH <i>Deled</i>	\$145.10	<i>45.40</i> \$145.10 ✓
6	1	REAR END PANEL <i>Regis</i>	\$668.00	\$668.00 <i>+</i>
7	1	REAR REVERSE SENSOR SPEAKER <i>new</i>	\$145.00	\$145.00 <i>+</i>
8	1	REAR TAILLAMP LH <i>new</i>	\$687.60	\$687.60 <i>+</i>

Reas Buyer Under cover 7H. 95.20 ✓
for

1478.80
1183.04

TOTAL : \$3,243.70
LESS 20 % \$648.74
SUB-TOTAL : \$2,594.96

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	2	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 <i>30</i>
2	2	REAR TAILLAMP CLIPS <i>new</i>	\$6.50	\$13.00 <i>+</i>
3	1	REAR END PANEL SEALANT <i>new</i>	\$80.00	\$80.00 <i>+</i>
4	1	REAR REVERSE SENSOR <i>new</i>	\$250.00	\$250.00 <i>+</i>

30

TOTAL: \$423.00

TOTAL PARTS: \$3,017.96

Labour charges

1	LABOUR FOR PANEL BEATING	\$600.00 300
2	LABOUR FOR SPRAYPAINTING	\$600.00 400
3	WIRING CHECK	\$80.00 30
4	TO APPLY RUST PROOF ON ACCIDENT AREAS	\$200.00 40 820
5	TO APPLY TUFF COATING ON ACCIDENT AREAS	\$200.00 x.
6	LABOUR FOR REMOVE & RENEW REAR REVERSE SENSOR	\$200.00 50

Subtotal :- \$1,880.00

Total:- \$4,897.96

A/S 11/05/24
03 Days.

2033.04
Total: ~~2003.04~~

A/S: 1.6K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: