

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SDS7088D

Model: HONDA SHUTTLE
(12/8/2016)

Accident Date : 30/4/2021

Location : BEDOK NORTH AVE 3

3P: SMT4290T (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Front n/s head lamp <i>cracked</i>	1,343.00	<i>x</i>	
2	1pc	Front n/s fender <i>pegs</i>	543.00	<i>x</i>	
3	1 pc	Front n/s tyre rim <i>cut</i>	-	1,600.00	400 (sn)
4	1 pc	Front bumper <i>delint</i>	1,050.50	<i>x</i>	
5	1 pc	Front bumper n/s retainer <i>xec</i>	71.30	<i>35</i>	
6	12 pcs	Front bumper clips <i>nu</i>	-	36.00	
Sub-Total:			3,007.80	1636.00	0.00
			20%	0%	10%
After Less %:			2,406.24	1636.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	800.00	<i>300</i>	
2		To spray painting.	1,000.00	<i>600</i>	
3		To remove & replace front n/s rim	80.00	<i>40</i>	
4		To check wiring	50.00	<i>30</i>	
Sub-Total:			1,930.00		
Total:			5,972.24		
After Less 20%:			4,777.79		

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

list: 2428
len 20%: 1942
SN: 436
Labour: 970

Admin *Ly*
H/S 24/05/21.
total: 3348 04 Days.
H/S: 2650



8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SDS7088D ESTIMATEPg1