

RICO 60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	26K

TO: MSIG

Vehicle No : SLN 1421 X

Make & Model : HONDA FIT

DATE: 10/5/2021

AK Xiong 81210478

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAIL GATE / DD	1	\$ 800 998.00	\$ 998.00
2	TAIL GATE WINDSCREEN MOULDING / NEC	1	\$ 125.00	\$ 125.00
3	TAIL GATE OUTER GARNISH ? / CRK	1	\$ 184.00	\$ 184.00
4	TAIL GATE OUTER GARNISH LOGO ? / NEC	1	\$ 58.00	\$ 58.00
5	TAIL GATE EMBLEM (FIT) / NEC	1	\$ 35.00	\$ 35.00
6	TAIL GATE EMBLEM (HYBRID) / NEC	1	\$ 35.00	\$ 35.00
7	TAIL GATE CAR PLATE LAMP XSVL	2	\$ 89.00	\$ 178.00
8	TAIL GATE OPENER HANDLE ? / CRK	1	\$ 144.80	\$ 144.80
9	TAIL GATE STOPPER ? XSVL	2	\$ 28.50	\$ 57.00
10	TAIL GATE POCKET HANDLE ? XSVL	1	\$ 54.00	\$ 54.00
11	TAIL GATE INNER TRIM ? / CRK	1	\$ 258.00	\$ 258.00
12	TAIL GATE INNER LOCK - jam	1	\$ 289.00	\$ 289.00
13	TAIL GATE LOCK CATCH - jam X NN	1	\$ 46.00	\$ 46.00
14	TAIL GATE WEATHER STRIP ? / TN	1	\$ 154.00	\$ 154.00
15	TAIL GATE DETECTOR ? / CRK	1	\$ 154.00	\$ 154.00
16	TAIL GATE DETECTOR WIREHARNESS ? XSVL / CNT	1	\$ 300 425.00	\$ 425.00
17	TAIL LAMP LED XSVL	2	\$ 450 524.00	\$ 1,048.00
18	REAR BUMPER / CRK	1	\$ 600 659.00	\$ 659.00
19	REAR BUMPER SIDE RETAINER ? / CRK	1	\$ 65.00	\$ 65.00
20	REAR BUMPER SIDE GRILLE ? / CRK	2	\$ 243.20	\$ 486.40
21	END PANEL ? / DD	1	\$ 550 655.00	\$ 655.00
22	END PANEL TOP GARNISH / DEF	1	\$ 154.00	\$ 154.00
23	REAR ALARM BUZZER ? / CRK	1	\$ 188.70	\$ 188.70
24	REAR FLOOR PANEL ? / DD X R	1	\$ 750 985.00	\$ 985.00
25	REAR FLOOR TOP BOARD ? / DEF X SVL	1	\$ 300 415.00	\$ 415.00
26	REAR FLOOR TOOLS BOX ?	1	\$ 321.00	\$ 321.00

\$4,280.90

27	REAR FENDER INNER TRIM ? / CRK	2	\$ 300 541.00	\$ 1,082.00	300
28	REAR FENDER INNER SHIELD ? X SVL	2	\$ 125.00	\$ 250.00	600
29	REAR EXHAUST TAIL PIPE ? / DD X R	1	\$ 700 898.00	\$ 898.00	700 X
30	REAR EXHAUST HEAD SEAL ? X NV	1	\$ 154.00	\$ 154.00	
31	REAR EXHAUST MOUNTING ? X SVL	2	\$ 38.00	\$ 76.00	
				\$ 300.00	
Subtotal :				\$ 10,631.90	
Less 20%				\$ 2,126.38	
Parts Total :				\$ 8,505.52	

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	REAR NUMBER PLATE X NV	1	\$ 50.00	\$ 50.00	
2	REAR BUMPER CLIP / NEC	1	\$ 60.00	\$ 60.00	30
3	TAIL LAMP CLIP X NV	1	\$ 30.00	\$ 30.00	
4	TAIL GATE SEALANT / NEC X NV	1	\$ 80.00	\$ 80.00	X
5	TAIL GATE INNER TRIM CLIP / NEC	1	\$ 50.00	\$ 50.00	20
6	TAIL GATE WINDSCREEN SEALANT / NEC	1	\$ 60.00	\$ 60.00	50
7	TAIL GATE WINDSCREEN INNER SEAL 2 X NV	1	\$ 60.00	\$ 60.00	
8	REAR FENDER INNER SHIELD CLIP ? X SVL	1	\$ 60.00	\$ 60.00	
9	REAR FENDER INNER TRIM CLIPS ? / NEC	1	\$ 60.00	\$ 60.00	30
10	REAR END PANEL INSULATION SEAL ? / NEC	1	\$ 80 150.00	\$ 150.00	80 30
11	REAR FLOOR PANEL INSULATION SEAL ? / NEC	1	\$ 80 150.00	\$ 150.00	80 30
12	REVERSE SENSOR ? X not working	1	\$ 220.00	\$ 220.00	200
13	REVERSE CAMERA X SVL	1	\$ 450.00	\$ 450.00	
14	Remove & Refit HYBRID Battery ? / NEC	1	\$ 1200	\$ 1200	
SPECIAL NETT				\$ 1,480.00	390

LABOUR			PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	800	\$	1,500.00
TO SPRAY PAINT AFFECTED AREA	800	\$	1,200.00
TUFF COAT	100	\$	250.00
WIRING CHECK	30	\$	50.00
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR		\$ 100	250.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$ 30	120.00
REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING		\$ 120	120.00
REMOVE AND REFIX TAILGATE WINDSCREEN		\$ 120	150.00
REMOVE AND REFIX HYBRID BATTERY WITH RESET		\$ 2	1,200.00
TRANSFER TAILGATE MECHANISM		\$ 50	150.00

CONDUCT WATER LEAKAGE TEST	XNN	\$ 50.00
REMOVE AND REFIX REAR EXHAUST	/80 X NN	\$ 250.00
LABOUR TOTAL		\$ 5,290.00
Total Parts Cost	\$	9,985.52
Total Labour Cost	\$	5,290.00
Total Repair Cost	\$	15,275.52

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

NAZ LXX

11/5/2021 1600

215

7 DAYS

AFTER REPAIR PHOTOS

PARTS \$4,580.90

LESS 20% \$3,664.47

S/NETT \$ 390.00

LABOUR \$ 2,170.00

TOTAL \$6,224.72

LESS US 20% \$ 4,979.78

LIS TOTAL \$5,000.00 / 5 REPAIR DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: