



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

LKK

RICO Office Use Only

Parts -20%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	26K

Al Xiong 81210478

TO: MSIG				
Vehicle No : SLN 1421 X				
Make & Model : HONDA FIT				
DATE: 10/5/2021				
No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAIL GATE / DD	1	\$ 998.00	\$ 998.00
2	TAIL GATE WINDSCREEN MOULDING / NEC	1	\$ 125.00	\$ 125.00
3	TAIL GATE OUTER GARNISH ? / CRK	1	\$ 184.00	\$ 184.00
4	TAIL GATE OUTER GARNISH LOGO ? / NEC	1	\$ 58.00	\$ 58.00
5	TAIL GATE EMBLEM (FIT) / NEC	1	\$ 35.00	\$ 35.00
6	TAIL GATE EMBLEM (HYBRID) / NEC	1	\$ 35.00	\$ 35.00
7	TAIL GATE CAR PLATE LAMP X SVL	2	\$ 89.00	\$ 178.00
8	TAIL GATE OPENER HANDLE ? / CRK	1	\$ 144.80	\$ 144.80
9	TAIL GATE STOPPER ? X SVL	2	\$ 28.50	\$ 57.00
10	TAIL GATE POCKET HANDLE ? X SVL	1	\$ 54.00	\$ 54.00
11	TAIL GATE INNER TRIM ? / CRK	1	\$ 258.00	\$ 258.00
12	TAIL GATE INNER LOCK - jam	1	\$ 289.00	\$ 289.00
13	TAIL GATE LOCK CATCH - jam	1	\$ 46.00	\$ 46.00
14	TAIL GATE WEATHER STRIP ? / TN	1	\$ 154.00	\$ 154.00
15	TAIL GATE DETECTOR ? / CRK	1	\$ 154.00	\$ 154.00
16	TAIL GATE DETECTOR WIREHARNES ? / CUT	1	\$ 425.00	\$ 425.00
17	TAIL LAMP LED X SVL	2	\$ 524.00	\$ 1,048.00
18	REAR BUMPER / CRK	1	\$ 659.00	\$ 659.00
19	REAR BUMPER SIDE RETAINER ? / CRK	1	\$ 65.00	\$ 65.00
20	REAR BUMPER SIDE GRILLE ? / CRK	2	\$ 243.20	\$ 486.40
21	END PANEL ? / DD	1	\$ 655.00	\$ 655.00
22	END PANEL TOP GARNISH / DEF	1	\$ 154.00	\$ 154.00
23	REAR ALARM BUZZER ? / CRK	1	\$ 188.70	\$ 188.70
24	REAR FLOOR PANEL ? / DD	1	\$ 985.00	\$ 985.00
25	REAR FLOOR TOP BOARD ? / DEF	1	\$ 415.00	\$ 415.00
26	REAR FLOOR TOOLS BOX ?	1	\$ 321.00	\$ 321.00

27	REAR FENDER INNER TRIM ? / CRK	2	\$	541.00	\$	1,082.00
28	REAR FENDER INNER SHIELD ? X SVL	2	\$	125.00	\$	250.00
29	REAR EXHAUST TAIL PIPE ? / DD	1	\$	898.00	\$	898.00
30	REAR EXHAUST HEAD SEAL ? X NV	1	\$	154.00	\$	154.00
31	REAR EXHAUST MOUNTING ? X SVL	2	\$	38.00	\$	76.00

Subtotal : \$ 10,631.90

Less 20% \$ 2,126.38

Parts Total : \$ 8,505.52

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR NUMBER PLATE X NV	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP / NEC	1	\$ 60.00	\$ 60.00
3	TAIL LAMP CLIP X NV	1	\$ 30.00	\$ 30.00
4	TAIL GATE SEALANT / NEC	1	\$ 80.00	\$ 80.00
5	TAIL GATE INNER TRIM CLIP / NEC	1	\$ 50.00	\$ 50.00
6	TAIL GATE WINDSCREEN SEALANT / NEC	1	\$ 60.00	\$ 60.00
7	TAIL GATE WINDSCREEN INNER SEAL X NV	1	\$ 60.00	\$ 60.00
8	REAR FENDER INNER SHIELD CLIP ? X SVL	1	\$ 60.00	\$ 60.00
9	REAR FENDER INNER TRIM CLIPS ? / NEC	1	\$ 60.00	\$ 60.00
10	REAR END PANEL INSULATION SEAL ? / NEC	1	\$ 150.00	\$ 150.00
11	REAR FLOOR PANEL INSULATION SEAL ? / NEC	1	\$ 150.00	\$ 150.00
12	REVERSE SENSOR ? * not working	1	\$ 220.00	\$ 220.00
13	REVERSE CAMERA X SVL	1	\$ 450.00	\$ 450.00
14	Remove & Refit HYBRID Battery ? / NEC	1	\$ 1200	\$ 1200 -

SPECIAL NETT \$ 1,480.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS 800	\$ 1,500.00
TO SPRAY PAINT AFFECTED AREA 800	\$ 1,200.00
TUFF COAT 100	\$ 250.00
WIRING CHECK 30	\$ 50.00
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 100 250.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 30 120.00
REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 120 120.00 30
REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120 150.00
REMOVE AND REFIX HYBRID BATTERY WITH RESET	\$? 1,200.00
TRANSFER TAILGATE MECHANISM	\$ 50 150.00

CONDUCT WATER LEAKAGE TEST	XNN	\$	50.00
REMOVE AND REFIX REAR EXHAUST	80	\$	250.00
LABOUR TOTAL		\$	5,290.00
Total Parts Cost		\$	9,985.52
Total Labour Cost		\$	5,290.00
Total Repair Cost		\$	15,275.52

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

NAZ LKK
11/5/2021 1600
L/S
7 DAYS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: