



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : GBF6472B
Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Handwritten notes: No of Accident, 11/5/21, 12 days, 2/35, take spec to the shop, LK - Marcus

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205521

Handwritten date: 11/03/2021

Table with 4 columns: S/No, Quantity, Description, Amount. Contains 39 items for car repair, including front bumper, grille, headlamps, and tailgate lid. Includes handwritten notes and checkmarks.



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF6472B
Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205521

S/No	Quantity	Description	Amount
LIST ITEMS			
40	1 p	tailgate lid caren emblem <i>nee</i>	\$ 28.00
41	1 pc	tailgate lid KIA emblem <i>nee</i>	\$ 35.00
42	1 pc	rear windscreen glass <i>Slotford</i>	\$ 1,258.00
43	1 pc	tailgate lid open level <i>17</i>	\$ 155.00
44	1 pc	tailgate lid number plate lamp <i>17</i>	\$ 78.80
45	1 pc	tailgate lid inner trim board <i>D.S</i>	\$ 153.00
46	6 ps	tailgate lid inner trim board clips @ \$4.50 <i>17</i>	\$ 27.00
47	1 pc	tailgate lid inner trim board - n/s <i>17</i>	\$ 99.80
48	1 pc	tailgate lid inner trim board - o/s <i>cu7</i>	\$ 99.80
49	6 ps	tailgate lid inner trim board clips - n/s @ \$4.50 <i>17</i>	\$ 27.00
50	6 ps	tailgate lid inner trim board clips - o/s @ \$4.50 <i>17</i>	\$ 27.00
51	1 pc	tailgate lid inner trim board - top <i>cu7</i>	\$ 253.00
52	6 ps	tailgate lid inner trim board - top clips @ \$4.50 <i>17</i>	\$ 27.00
53	1 pc	rear wiper <i>17</i>	\$ 85.00
54	1 pc	rear wiper motor <i>17</i>	\$ 401.00
55	1 pc	tailgate lid weatherstrip <i>TW1</i>	\$ 115.00
56	1 pc	rear end panel <i>Bolbor</i>	\$ 611.00
57	1 pc	rear end panel top garnish	\$ 123.00
58	6 ps	rear end panel top garnish clips @ \$4.50 <i>17</i>	\$ 27.00
59	1 pc	taillamp o/s <i>520</i>	\$ 525.00
60	4 ps	taillamp clip o/s @ \$5.50 <i>nee</i>	\$ 22.00
61	1 pc	taillamp panel o/s <i>D.S</i>	\$ 155.00
62	1 pc	floor panel <i>12</i>	\$ 989.00
63	1 pc	floor panel board <i>17</i>	\$ 515.00
64	1 pc	floor panel tool compartment tray	\$ 279.00
65	1 pc	o/s rear safety belt	\$ 1,389.00
66	6 ps	roof lining clips @ \$4.50 <i>17</i>	\$ 27.00
67	1 pc	o/s rear 1/4 glass with outer chrome moulding <i>Surf</i>	\$ 334.00
68	1 pc	o/s rear 1/4 glass inner garnish - top <i>DL</i>	\$ 75.00
69	1 pc	o/s rear 1/4 glass inner garnish - lower <i>D.S</i>	\$ 75.00
70	1 pc	o/s rear fender <i>D.S</i>	\$ 1,349.00
71	1 pc	o/s rear fender inner cowling <i>7.12</i>	\$ 202.00
72	8 ps	o/s rear fender inner cowling clips @ \$5.50 <i>nee</i>	\$ 44.00
73	1 pc	roof top lining <i>17</i>	\$ 985.00
74	1 pc	rear axle	\$ 1,161.00
75	1 pc	rear axle housing <i>12</i>	\$ 1,986.00
76	1 pc	o/s rear axle bracket	\$ 85.00
77	1 pc	o/s rear shock absorber	\$ 200.00
78	1 pc	o/s rear wheel bearing	\$ 345.00



陳林摩摩私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF6472B
 Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
 Chassis No : KNAHU815VJ7205521

S/No	Quantity	Description	Amount
LIST ITEMS			
79	1 pc	o/s rear exhaust box <i>14</i>	\$ 811.00 <i>X</i>
80	1 pc	o/s rear exhaust box mounting <i>11</i>	\$ 39.00 <i>X</i>
		Less 10 %	\$ 28,041.70
			\$ 2,804.17
			\$ 25,237.53
SPECIAL NETT ITEMS			
81	1 pc	front licence plate <i>sent</i>	\$ 50.00 <i>40</i>
82	1 pc	rear windscreen primer <i>nee</i>	\$ 40.00 <i>30</i>
83	1 pc	rear windscreen inner sponge seal <i>nee</i>	\$ 80.00 <i>30</i>
84	1 pc	rear windscreen sealant <i>nee</i>	\$ 120.00 <i>40</i>
85	1 pc	o/s rear wheel sport rim <i>sent</i>	\$ 450.00 <i>350</i>
86	1 pc	o/s rear wheel tyre <i>eng 1200</i>	\$ 220.00 <i>60% 120</i>
87	1 pc	o/s rear 1/4 glass seal <i>nee</i>	\$ 50.00 <i>40</i>
88	1 pc	o/s rear 1/4 glass sealant <i>Repull</i>	\$ 40.00 <i>X</i>
			\$ 1,050.00
LABOUR & MISC. CHARGES			
01		To remove and refit rear right fender 1/4 glass.	\$ 100.00 <i>60</i>
02		To check electrical lighting concerned.	\$ 100.00 <i>30</i>
03		To upholstery and make good repair to cushion seat and seat frame and reclining mechanism.	\$ 200.00 <i>80</i>
04		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 100.00 <i>?</i>
05		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 360.00 <i>X</i>
06		To drop rear exhaust box and renew the same.	\$ 11 100.00 <i>X</i>
07		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 11 350.00 <i>X</i>
08		To transfer of tyre, rim and on wheel balancing.	\$ 11 50.00 <i>X</i>
09		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 11 250.00 <i>X</i>
10		To reinstall of rear bumper parking sensor.	\$ 120.00 <i>50</i>
11		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 140.00 <i>60</i>
12		To remove and refit rear windscreen glass.	\$ 140.00 <i>120</i>
13		To rust-proofing of the affected areas.	\$ 300.00 <i>120</i>
14		To check steering geometry and computer wheel alignment.	\$ 120.00 <i>80</i>
15		Towing charges.	\$ 150.00 <i>100</i>



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF6472B
Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205521

S/No	Quantity	Description	Amount
16		LABOUR & MISC. CHARGES	
		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00
17		Putty and spray painting of the affected portion.	\$ 2,600.00
			\$ 6,980.00
		Total	\$ 33,267.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1600
1800