

444 H5c40704



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : GBF6472B
Date of Accident : 10 May 2021

Not Approved
11/5/21
12 days
2/3 # 15,400
take photo of the car
LXK - Marcus

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205521

11/03/2021 0900h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>DD/De</i>	\$ 627.00
02	1 pc	front bumper centre grille <i>Top</i>	\$ 150.00
03	8 ps	front bumper clips @ \$5.00 <i>rec</i>	\$ 40.00
04	1 pc	front bumper diffuser <i>De/Top</i>	\$ 167.00
05	2 ps	front bumper side retainer @ \$21.00 <i>17</i>	\$ 42.00
06	2 ps	front bumper fog lamp @ \$186.00 <i>17</i>	\$ 372.00
07	2 ps	front bumper fog lamp trim @ \$118.00 <i>17</i>	\$ 236.00
08	1 pc	front bumper foam <i>Top</i>	\$ 61.00
09	1 pc	front bumper beam - top <i>Self</i>	\$ 351.00
10	1 pc	front bumper beam - bottom <i>17</i>	\$ 81.00
11	1 pc	front bumper emblem <i>rec</i>	\$ 68.00
12	1 pc	front bumper top rubber seal <i>17</i>	\$ 25.00
13	1 pc	front grille <i>one</i>	\$ 425.00
14	1 pc	front grille outer ring <i>complete</i>	\$ 85.00
15	1 pc	front grille holder	\$ 45.00
16	2 ps	headlamp @ \$1559.00 <i>holder cover 15x8x25 3116</i>	\$ 3,118.00
17	2 ps	headlamp bracket @ \$11.00 <i>nn</i>	\$ 22.00
18	1 pc	bonnet <i>DD/Buc</i>	\$ 831.00
19	6 ps	bonnet insulator clips @ \$4.30 <i>CRA</i>	\$ 25.80
20	1 pc	front support panel <i>R</i>	\$ 567.00
21	1 pc	front support panel top garnish <i>one</i>	\$ 46.00
22	5 ps	front support panel top garnish clips @ \$4.30 <i>17</i>	\$ 21.50
23	1 pc	rear bumper <i>D.S</i>	\$ 452.00
24	10 ps	rear bumper clips @ \$5.00 <i>rec</i>	\$ 50.00
25	2 ps	rear bumper side retainer @ \$23.00 <i>1/scene</i>	\$ 46.00
26	1 pc	rear bumper lower <i>D.S</i>	\$ 179.00
27	1 pc	rear bumper defussion <i>R</i>	\$ 186.00
28	1 pc	rear bumper beam <i>one</i>	\$ 341 367.00
29	2 ps	rear bumper beam bracket @ \$84.00 <i>o/s self</i>	\$ 168.00
30	2 ps	rear bumper top bracket @ \$25.00 <i>o/s self</i>	\$ 50.00
31	3 ps	rear bumper lower bracket @ \$27.00 <i>o/s self</i>	\$ 81.00
32	4 ps	rear bumper parking sensor @ \$160.00 <i>Top o/s</i>	\$ 640.00
33	4 ps	rear bumper parking sensor holder @ \$65.00 <i>17</i>	\$ 260.00
34	1 pc	rear bumper reflector o/s <i>370</i>	\$ 116.00
35	1 pc	tailgate lid <i>3.05107</i>	\$ 1,088.00
36	1 pc	tailgate lid reflector o/s <i>370</i>	\$ 773.00
37	1 pc	tailgate lid reflector n/s <i>17</i>	\$ 773.00
38	1 pc	tailgate lid outer garnish <i>one</i>	\$ 153.00
39	1 pc	tailgate lid CRDi emblem <i>rec</i>	\$ 31.00

8991.8



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF6472B
Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205521

S/No	Quantity	Description	Amount
LIST ITEMS			
40	1 p	tailgate lid caren emblem <i>nee</i>	\$ 28.00
41	1 pc	tailgate lid KIA emblem <i>nee</i>	\$ 35.00
42	1 pc	rear windscreen glass <i>shoffland 490</i>	\$ 1,258.00
43	1 pc	tailgate lid open level <i>17</i>	\$ 155.00
44	1 pc	tailgate lid number plate lamp <i>17</i>	\$ 78.80
45	1 pc	tailgate lid inner trim board <i>D.S</i>	\$ 153.00
46	6 ps	tailgate lid inner trim board clips @ \$4.50 <i>17</i>	\$ 27.00
47	1 pc	tailgate lid inner trim board - n/s <i>17</i>	\$ 99.80
48	1 pc	tailgate lid inner trim board - o/s <i>cut</i>	\$ 99.80
49	6 ps	tailgate lid inner trim board clips - n/s @ \$4.50 <i>17</i>	\$ 27.00
50	6 ps	tailgate lid inner trim board clips - o/s @ \$4.50 <i>17</i>	\$ 27.00
51	1 pc	tailgate lid inner trim board - top <i>cut</i>	\$ 253.00
52	6 ps	tailgate lid inner trim board - top clips @ \$4.50 <i>17</i>	\$ 27.00
53	1 pc	rear wiper <i>17</i>	\$ 85.00
54	1 pc	rear wiper motor <i>17</i>	\$ 401.00
55	1 pc	tailgate lid weatherstrip <i>new</i>	\$ 115.00
56	1 pc	rear end panel <i>30d600</i>	\$ 611.00
57	1 pc	rear end panel top garnish <i>17</i>	\$ 123.00
58	6 ps	rear end panel top garnish clips @ \$4.50 <i>17</i>	\$ 27.00
59	1 pc	taillamp o/s <i>bro 357</i>	\$ 525.00
60	4 ps	taillamp clip o/s @ \$5.50 <i>nee</i>	\$ 22.00
61	1 pc	taillamp panel o/s <i>D.S</i>	\$ 155.00
62	1 pc	floor panel <i>12</i>	\$ 989.00
63	1 pc	floor panel board <i>17</i>	\$ 515.00
64	1 pc	floor panel tool compartment tray <i>17</i>	\$ 279.00
65	1 pc	o/s rear safety belt <i>crokm 980</i>	\$ 1,389.00
66	6 ps	roof lining clips @ \$4.50 <i>17</i>	\$ 27.00
67	1 pc	o/s rear 1/4 glass with outer chrome moulding <i>sent</i>	\$ 334.00
68	1 pc	o/s rear 1/4 glass inner garnish - top <i>DE</i>	\$ 75.00
69	1 pc	o/s rear 1/4 glass inner garnish - lower <i>D.S</i>	\$ 75.00
70	1 pc	o/s rear fender <i>D.S</i>	\$ 1,349.00
71	1 pc	o/s rear fender inner cowling <i>7011</i>	\$ 202.00
72	8 ps	o/s rear fender inner cowling clips @ \$5.50 <i>nee</i>	\$ 44.00
73	1 pc	roof top lining <i>17</i>	\$ 985.00
74	1 pc	rear axle <i>sent/nee 1160</i>	\$ 1,161.00
75	1 pc	rear axle housing <i>NS</i>	\$ 1,986.00
76	1 pc	o/s rear axle bracket <i>17</i>	\$ 85.00
77	1 pc	o/s rear shock absorber <i>17</i>	\$ 200.00
78	1 pc	o/s rear wheel bearing <i>Dayed</i>	\$ 345.00



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF6472B
Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205521

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
79	1 pc	o/s rear exhaust box <i>ny</i>	\$ 811.00
80	1 pc	o/s rear exhaust box mounting <i>11</i>	\$ 39.00
			\$ 28,041.70
		Less 10 %	\$ 2,804.17
			\$ 25,237.53
<u>SPECIAL NETT ITEMS</u>			
81	1 pc	front licence plate <i>sent</i>	\$ 50.00
82	1 pc	rear windscreen primer <i>rec</i>	\$ 40.00
83	1 pc	rear windscreen inner sponge seal <i>rec</i>	\$ 80.00
84	1 pc	rear windscreen sealant <i>rec</i>	\$ 120.00
85	1 pc	o/s rear wheel sport rim <i>sent</i>	\$ 450.00
86	1 pc	o/s rear wheel tyre <i>cut 1P200</i>	\$ 220.00
87	1 pc	o/s rear 1/4 glass seal <i>rec</i>	\$ 50.00
88	1 pc	o/s rear 1/4 glass sealant <i>Repalt</i>	\$ 40.00
			\$ 1,050.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear right fender 1/4 glass.	\$ 100.00
02		To check electrical lighting concerned.	\$ 100.00
03		To upholstery and make good repair to cushion seat and seat frame and reclining mechanism.	\$ 200.00
04		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 100.00
05		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 360.00
06		To drop rear exhaust box and renew the same.	\$ 11 100.00
07		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 11 350.00
08		To transfer of tyre, rim and on wheel balancing.	\$ 11 50.00
09		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 11 250.00
10		To reinstall of rear bumper parking sensor.	\$ 120.00
11		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 140.00
12		To remove and refit rear windscreen glass.	\$ 140.00
13		To rust-proofing of the affected areas.	\$ 300.00
14		To check steering geometry and computer wheel alignment.	\$ 120.00
15		Towing charges.	\$ 150.00

X
X

40
30
30
40
350
602 120
40
X

60
30
20

250
X
X
X
50
60
120
120
80
100



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF6472B
 Date of Accident : 10 May 2021

Messrs BIS Motoring Pte Ltd

Date : 10 May 2021

Estimate To Repair SLZ2866B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
 Chassis No : KNAHU815VJ7205521

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
16		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00
17		Putty and spray painting of the affected portion.	\$ 2,600.00
			\$ 6,980.00
		Total	\$ 33,267.53

1600
1800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 15874.60
 102
 9- 14287.14
 S.M- 650.00
 L- 4350.00
 19287.14
 297
 15429.