

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SLM7360D [YOUR INSURED] & GBJ1580J [OUR CLIENT]
ON 08/05/2021.

ESTIMATED REPAIR COSTS FOR GBJ1580J

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	SIDE MIRROR RECTANGLE LH HH	\$ 762.30	X
1PC	SIDE MIRROR ROUND LH HH	\$ 418.70	X
1PC	SIDE MIRROR STAY LH HH	\$ 399.10	X
1PC	SIDE MIRROR GARNISH LH HH <i>corner panel</i> 233.00	\$ 298.90	X ✓
1PC	FRONT PANEL HH <i>cut 1 Bt.</i>	\$ 1,021.20	X
1PC	FRONT PANEL 'DYNA' EMBLEM HH	\$ 76.20	X
1PC	FRONT GRILLE HH	\$ 692.00	X
1PC	FRONT GRILLE BASE HH	\$ 711.00	X
1PC	FRONT GRILLE LOGO HH	\$ 69.00	X
1PC	HEAD LAMP LH <i>Scratched</i> 745.20	\$ 872.70	✓
1PC	HEAD LAMP WIRE HARNESS HH	\$ 1,142.90	X
1PC	FRONT BUMPER <i>1st</i> 476.30	\$ 692.80	✓
1PC	FRONT BUMPER BEAM HH	\$ 822.10	X
1PC	FRONT BUMPER FOG LAMP GARNISH LH HH	\$ 129.00	X
1PC	FRONT WINDSCREEN MOULDING <i>HH</i> HH	\$ 295.90	X
1PC	A PILLAR LH HH	\$ 1,249.80	X
1PC	FRONT DOOR LH <i>1st / Dented</i> 1349.10	\$ 1,789.20	✓
1PC	FRONT DOOR WINDOW MOULDING LOWER LH HH	\$ 198.80	X
1PC	FRONT DOOR WINDOW MOULDING UPPER LH <i>SVL</i>	\$ 171.50	X
2PCS	FRONT DOOR HINGE LH @ \$79.00 EACH HH	\$ 158.00	X
1PC	FRONT DOOR INNER TRIM BOARD LH HH	\$ 1,141.90	X
1PC	FRONT DOOR WINDOW MOTOR LH HH	\$ 712.90	X
1PC	FRONT DOOR WINDOW REGULATOR LH HH	\$ 320.40	X
1PC	FRONT DOOR LOCK LH HH	\$ 295.10	X
1PC	FRONT DOOR LAMP LH <i>cut</i> 145.00	\$ 239.40	✓
1PC	FRONT DOOR WEATHER STRIP LH HH	\$ 289.10	X
1PC	FRONT DOOR STEP GARNISH LH HH	\$ 198.20	X
1PC	FRONT WHEEL HOUSING LH HH	\$ 1,890.00	X
1PC	FRONT WHEEL HOUSING TOP GARNISH LH HH	\$ 289.40	X
1PC	FRONT WHEEL HOUSING INNER COWLING LH HH	\$ 301.90	X

2PCS	FRONT RIM LH HJ	\$ 1,706.20	X
2PCS	FRONT WHEEL BEARING LH HJ	\$ 479.40	X
2PCS	FRONT WHEEL BEARING HUB LH HJ	\$ 684.20	X
2PCS	FRONT KNUCKLE ARM LH HJ	\$ 2,090.00	X
2PCS	FRONT LOWER ARM LH HJ	\$ 1,196.20	X
2PCS	FRONT UPPER ARM LH HJ	\$ 1,442.00	X
2PCS	FRONT ABSORBER LH HJ	\$ 956.40	X
2PCS	FRONT TIE ROD LH HJ	\$ 498.20	X
2PCS	FRONT TIE ROD END LH HJ	\$ 578.40	X
2PCS	FRONT STABILIZER LINK LH HJ	\$ 396.40	X
1PC	FRONT STABILIZER BAR HJ	\$ 629.30	X
1PC	STEERING RACK & PINION ASSY HJ	\$ 2,247.10	X
1PC	A/C CONDENSOR ASSY HJ	\$ 1,302.40	X
1PC	A/C DISCHARGE HOSE HJ	\$ 598.20	X
1PC	A/C SUCTION HOSE HJ	\$ 692.40	X
1PC	A/C CONDENSOR COWLING HJ	\$ 498.20	X

PARTS SUM: \$ 33,644.40

PARTS LESS 25%: \$ 8,411.10

PARTS TOTAL: \$ 25,233.30

2948.60

2211.45

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1PC TYRE HJ	\$ 300.00	X
*	TO SUPPLY FRONT DOOR COMPANY STICKER HJ	\$ 50.00	30/-
*	TO SUPPLY FRONT WINDSCREEN SEALANT HJ	\$ 80.00	X
*	TO SUPPLY FRONT WINDSCREEN DAMPING SEAL HJ	\$ 30.00	X
*	TO SUPPLY FRONT WINDSCREEN INNER SEAL HJ	\$ 50.00	X
*	TO SUPPLY FRONT PANEL SEALANT HJ	\$ 50.00	X
*	TO SUPPLY FRONT GRILLE CLIPS HJ	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS HJ	\$ 50.00	X
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS HJ	\$ 50.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	HJ
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 3,000.00	600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 3,000.00	600/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	\$ 200.00	HJ
*	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	\$ 150.00	HJ
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00	HJ
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00	HJ

- * TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS \$ 250.00 60/-
- * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS 1330.00 \$ 200.00 30/-

LABOUR & S/N TOTAL: \$ 8,630.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 33,863.30


11/05/2021 @ 1730hrs

H/A Andrew

2/Sum 4
B dgs.

1 ryan

LKK Auto



Check Part Prices.

3571.45

2/s 2,500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: