



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/ KENDA (S) PTE LTD
	Reg No/Reg Date	GBH6076B / 03/08/201
	Date In/Mileage	/ 0
	Chassis No	KNCSJX76LH7194556
	Engine No	D4CBH321575
	Make/Model	KIACV/K2500 BSP EURO 6
	Colour/Trim	UD CLEAR WHITE / GW GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	11/05/2021/ 11:55	BLE	261 / Edwin Caina	33254			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								
RESERVOIR ASSY-RADIATOR								
KS254314E013								2000.00
E PNT88000								
RENEW FRT BUMPER & BONNET								
REPAIR FRT PNL								700.00
E PNT98000								
RESPRAY FRT PANEL & BONNET								200.00
A 25000001								
RENEW AIRCON PIPE								80.00
A 25000001								
TOP UP AIRCON GAS								200.00
A 25000001								
RENEW AIRCON BLOWER ASSY								400.00
A 25000001								
REMOVE & REFIT DASHBOARD ASSY								30.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								60.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								50.00
M SUNDRY								
SUPPLY FRT NUMBER PLATE WITH CASING								80.00
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								20.00
M SUNDRY								
Sundries								
M COVER-FR BUMPER					1.00	365.00	20.00	292.00
M MESH-FRONT BUMPER CENTER,UPR					1.00	42.00	20.00	33.60
M MESH-FRONT BUMPER CENTER,LWR					1.00	42.00	20.00	33.60
M MOULDING-FRT BPR LICENSE PLATE					1.00	26.00	20.00	20.80
M GARNISH-HOOD					1.00	203.00	20.00	162.40
M RAIL ASSY-FR BUMPER					1.00	329.00	20.00	263.20

# Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/ KENDA (S) PTE LTD
	Reg No/Reg Date	GBH6076B / 03/08/201
	Date In/Mileage	/ 0
	Chassis No	KNCSJX76LH7194556
	Engine No	D4CBH321575
	Make/Model	KIACV/K2500 BSP EURO 6
	Colour/Trim	UD CLEAR WHITE / GW GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	11/05/2021/ 11:55	BLE	261 / Edwin Caina	33254			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET ASSY-FR BUMPER SIDE,LH	1.00	42.00	20.00	33.60			
M	BRACKET ASSY-FR BUMPER SIDE,RH	1.00	42.00	20.00	33.60			
M	COVER-BLANKING FR FOG LH	1.00	14.00	20.00	11.20			
M	COVER-BLANKING FRT FOG,RH	1.00	14.00	20.00	11.20			
M	PANEL ASSY-HOOD	1.00	349.00	20.00	279.20			
M	HINGE ASSY-HOOD,LH	1.00	63.00	20.00	50.40			
M	HINGE ASSY-HOOD,RH	1.00	63.00	20.00	50.40			
M	W/STRIP-HOOD	1.00	29.00	20.00	23.20			
M	LATCH ASSY-HOOD	1.00	55.00	20.00	44.00			
M	LOGO ASSY-KIA SUB	1.00	86.00	20.00	68.80			
M	RESERVOIR & PUMP ASSY-WASHER	1.00	89.00	20.00	71.20			
M	CASE ASSY-AIR INLET DUCT	1.00	55.00	20.00	44.00			
M	HEATER COMPLETE	1.00	2448.00	20.00	1958.40			
M	LAMP ASSY-HEAD,LH	1.00	340.00	20.00	272.00			
M	LAMP ASSY-HEAD,RH	1.00	340.00	20.00	272.00			
M	TUBE ASSY-SUCTION & LIQUID	1.00	697.00	20.00	557.60			
M	COOLANT (4L)	1.00	26.00	23.00	20.02			
SURVEYOR NAME : _____ SURVEYOR SIGNATURE : _____ DATE : _____ REMARKS : _____								

Confirm & accepted by

	Nett	8,426.42
7% GST on	8426.42	589.85
<b>Total Payable</b>		<b>9,016.27</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.