



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
GOH MENG SAN, DAPHNY (WU MINGSHAN) Blk 677b Punggol Drive #06-782 Singapore 822677 Contact No	Cust No/Name KCV18392/GOH MENG SAN, DAPHNY (WU MINGSHAN) Reg No/Reg Date SLU475K / 21/11/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH000597 Engine No 3A92UGL9872 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV18392	CRDVCH	11/05/2021/ 13:09	BLC	442 / CocoLu	10920

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT FENDER LH, FRT BUMPER, WINDMIRROR LH	1	1050.00		1050.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, WINDMIRROR LH	1	30.00		30.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM	1	120.00		120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	1	30.00		30.00
M SUNDRY TRANSFER FRT LEFT RIM	1	120.00		120.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment	1	20.00		20.00
M SUNDRY Sundry	1.00	706.00	00.00	706.00
M FACE,FR BUMPER	1.00	165.00	00.00	165.00
M GRILLE,FR UNDER	1.00	127.00	00.00	127.00
M GARNISH,FR BUMPER,LH	1.00	13.00	00.00	13.00
M BRACKET,FR BUMPER,LH	1.00	500.00	00.00	500.00
M FENDER,FR LH	1.00	98.00	00.00	98.00
M SHIELD,FR WHEELHOUSE,LH	1.00	641.00	00.00	641.00
M MIRROR ASSY,DOOR,LH	1.00	115.00	00.00	115.00
M COVER,DOOR MIRROR,OTR LH	1.00	663.00	00.00	663.00
M HEADLAMP ASSY,LH	1.00	687.00	00.00	687.00
M WHEEL,DISC (FR LH) CUT AFTER ty polish)	1.00	687.00	00.00	687.00

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate

Steve CLKK) 00-NH AL
 11/5/21, 2:00pm EXCESS - ?
 PIP
 M DOL SK

Confirmed Accepted by	Nett	Amount
5 days	6285.00	6,285.00
7% GST on	439.95	439.95
Total Payable		6,724.95

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.