



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
GOH MENG SAN, DAPHNY (WU MINGSHAN) Blk 677b Punggol Drive #06-782 Singapore 822677 Contact No	Cust No/Name KCV18392/GOH MENG SAN, DAPHNY (WU MINGSH) Reg No/Reg Date SLU475K / 21/11/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH000597 Engine No 3A92UGL9872 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV18392	CRDVCH	11/05/2021/ 13:09	BLC	442 / CocoLu	10920

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT FENDER LH, FRT BUMPER, WINDMIRROR LH	1-5 X 450			675 1200.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, WINDMIRROR LH	80 2 p4 + 80			780 1050.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				30.00
M SUNDRY TRANSFER FRT LEFT RIM				120.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				20.00
M SUNDRY Sundry	1.00	706.00	00.00	706.00
M FACE, FR BUMPER / 00	1.00	165.00	00.00	165.00
M GRILLE, FR UNDER ? X N/A	1.00	127.00	00.00	127.00
M GARNISH, FR BUMPER, LH ? X N/A	1.00	13.00	00.00	13.00
M BRACKET, FR BUMPER, LH / BR	1.00	500.00	00.00	500.00
M FENDER, FR LH / 00	1.00	98.00	00.00	98.00
M SHIELD, FR WHEELHOUSE, LH ? X N/A	1.00	641.00	00.00	641.00
M MIRROR ASSY, DOOR, LH / BR	1.00	115.00	00.00	115.00
M COVER, DOOR MIRROR, OTR LH X R	1.00	663.00	00.00	663.00
M HEADLAMP ASSY, LH / BR	1.00	687.00	00.00	687.00
M WHEEL, DISC (FR LH) / CUT (After tyg polish)	1.00	687.00	00.00	687.00

Estimate

Steve CLKK) 00 - N/A AL
 11/5/21, 2.00pm EXCESS - ?
 PIP
 M Del SKY

<p>Confirmed & accepted by</p> <ul style="list-style-type: none"> To resurvey before/after repair To display damaged parts for resurvey Parts prices are subject to fluctuation Third party survey is done without prejudice basis No illegal modifications allowed <p>Supplement to estimate to be surveyed and approved by the company</p> <p>Authorized signatory and company stamp</p>	<p>5 dys</p> <p>7% GST on</p> <p>Nett 6285.00</p> <p>Total Payable 6,724.95</p>
---	---

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.