

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	✓	🖨	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UI021005722/Atf3 Date: 11/05/2021 Code: UI02	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 2395A		Veh. Inspected	SKU 492Y
Policy No.			Coverage (\$)	0.00
Claim No.	M12D15662105		Excess (\$)	0.00
Assign From	JOSEPHINE WONG		Assign Date	11/05/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/05/2021		Inspection Date	11/05/2021
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				