

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AXA INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SHC8931A [YOUR INSURED] & SMN3360M [OUR CLIENT]
ON 08/05/2021.

ESTIMATED REPAIR COSTS FOR SMN3360M

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BOOTLID HW	\$ 1,982.40	X
1PC	BOOTLID 'HYUNDAI' LOGO HW	\$ 196.20	X
1PC	BOOTLID 'AVANTE' EMBLEM HW	\$ 61.20	X
1PC	BOOTLID REVERSE CAMERA HW	\$ 926.10	X
1PC	BOOTLID LOCK HW	\$ 216.20	X
1PC	BOOTLID INNER TRIM HW	\$ 246.80	X
2PC	BOOTLID LAMP L+R @ \$484.90 EACH HW	\$ 969.80	X
1PC	BOOTLID WEATHER STRIP HW	\$ 292.50	Y
1PC	REAR BUMPER <i>denture / deformed</i>	\$ 659.40	✓
1PC	REAR BUMPER BRACKET HW	\$ 178.60	X
2PC	REAR BUMPER SIDE RETAINER L+R @ \$59.40 EACH SW	\$ 118.80	X
1PC	REAR BUMPER CENTER GARNISH <i>cut / scratched</i> H/S <i>broken</i> / <i>SW</i>	\$ 553.50	✓
2PC	REAR BUMPER CENTER GARNISH REFLECTOR L+R @ \$301.50 EACH	\$ 603.00	X
2PC	REAR BUMPER CENTER GARNISH LAMP L+R @ \$799.80 EACH HW	\$ 1,599.60	X
2PC	REAR BUMPER NO. PLATE LAMP L+R @ \$118.20 EACH HW H/S	\$ 236.40	X
2PC	TAIL LAMP L+R @ \$635.10 EACH HW	\$ 1,270.20	X
2PC	TAIL LAMP LOWER BRACKET L+R @ \$293.10 EACH HW	\$ 586.20	X
1PC	REAR REINFORCEMENT BAR <i>broken</i>	\$ 694.80	✓
1PC	REAR KEYLESS SENSOR HW	\$ 244.50	X
1PC	REAR END PANEL <i>denture</i>	\$ 754.60	X
1PC	REAR END PANEL TOP GARNISH HW	\$ 259.80	X
1PC	SPARE WHEEL PANEL HW	\$ 1,491.00	X
1PC	SPARE WHEEL PANEL TOP BOARD HW	\$ 394.00	X
1PC	SPARE WHEEL PANEL TOOL BOX HW	\$ 351.00	X
2PCS	REAR REINFORCEMENT BAR HOLDER LH/RH @ \$299.30 EACH	\$ 597.40	✓
1 PC	REAR BUMPER NO. PLATE BASE \$198.20 <i>deformed</i>	PARTS SUM: \$ 14,886.60	
1 PC	REAR BUMPER UNDERCOVER LH \$223.10 HW	PARTS LESS 20%: \$ 2,977.32	
		PARTS TOTAL: \$ 11,909.28	

X

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1 SET REAR REVERSE SENSOR SVL	\$ 300.00 X 40/-
*	TO SUPPLY REAR END PANEL SEALANT HEC	\$ 80.00 50/-
*	TO SUPPLY REAR NUMBER PLATE M+	\$ 40.00 ✓
*	TO SUPPLY REAR BUMPER CLIPS HEC	\$ 50.00 20/-
*	TO SUPPLY REAR BOOTLID INNER TRIM CLIPS HH	\$ 50.00 X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00 ^{500/-} 300/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00 ^{500/-} 350/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 120/- 40/-
*	TO RNR REVERSE CAMERA	\$ 100.00 HH
*	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00 HH
*	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00 HH
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00 HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 HH
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 HH
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$ 120.00 40/-

LABOUR & S/N TOTAL: \$ 6,540.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 18,449.28

11/05/2021 @ 1700hrs

WAT Andrew

Tygar

2kk Auto

Check part prices

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: