


Make/Model: MITSUBISHI LANCER CS3
Engine/Chassis No.:
Date of accident:
Damaged area: Front

Date: 11/05/2021
Claim Type: TP
VRN: SMS1229Y

Not Notified
11 Sep 8 7200hr
Presurvey After Paim
6 days



List items

S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet 629	Bu 1	\$ 968.00	\$ 968.00
2	Bonnet lock 101	Bu 1	\$ 187.00	\$ 187.00
3	Bonnet hinge @ 116	Di 2	\$ 143.00	\$ 286.00
4	Coolant expansion tank	nd 1	\$ 125.00	\$ 125.00
5	Bonnet weatherstrip	GM 2	\$ 54.00	\$ 216.00
6	Front fender C526-90	N/S Bu 2	\$ 877.00	\$ 1,754.00
7	Front fender cowl	Sm 2	\$ 171.00	\$ 342.00
8	Front bumper lower side cowl n/s	Sm 1	\$ 58.00	\$ 58.00
9	Headlamp o/s m/c	N/S Bu 2	\$ 836.00	\$ 1,672.00
10	Headlamp lower bracket	At 2	\$ 105.00	\$ 210.00
11	Headlamp support panel	Recess At 12	\$ 457.00	\$ 914.00
12	Headlamp top bracket	R 2	\$ 267.00	\$ 534.00
13	Front bumper 710	At/Cat 1	\$ 799.00	\$ 799.00
14	Radiator assy 802	Bu/Pu 1	\$ 837.00	\$ 837.00
15	Radiator fan assy 306	Cat 1	\$ 455.00	\$ 455.00
16	Front bumper side retainer	Di 2	\$ 78.00	\$ 156.00
17	Front bumper bracket	N/S Bu 2	\$ 69.00	\$ 138.00
18	Radiator grille 256	Cat 1	\$ 578.00	\$ 578.00
19	Front bumper lower lip	Sm 1	\$ 280.00	\$ 280.00
20	Radiator grille "MITSUBISHI" logo	Nu 1	\$ 56.00	\$ 56.00
21	Front bumper lower grille 85	Di 1	\$ 295.00	\$ 295.00
22	Front fog lamp	Sm 2	\$ 377.00	\$ 754.00
23	Fog lamp garnish	Sm 2	\$ 169.00	\$ 338.00
24	A/C condenser	Bu 1	\$ 773.00	\$ 773.00
25	Front bumper sponge	NIP 1	\$ 187.00	\$ 187.00
26	Front bumper reinforcement 168	Bu 1	\$ 557.00	\$ 557.00
27	Front support panel 659	Bu 1	\$ 675.00	\$ 675.00
28	A/C condenser fan assy 380	Cat 1	\$ 512.00	\$ 512.00
29	Air filter housing	Cat 1	\$ 237.00	\$ 237.00
30	Front bumper licence plate garnish	Nu 1	\$ 78.00	\$ 78.00

1
1
1
1
4
4
X
X
1
X
X
1
2
2
1
4
1
X
1
1
X
X
2
X
1
1
2
2
1