

Repair Estimate

31	Battery tray	1	\$ 49.00	\$ <i>sn</i> 49.00	X
32	Subframe assy lower	1	\$ 664.00	\$ <i>sn</i> 664.00	X
Subtotal				\$ 15,684.00	
List discount				10.00%	
Total				\$ 14,115.60	

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper lower lip sealant	1	\$ 100.00	\$ 100.00
2	Air filter element	1	\$ 55.00	\$ 55.00
3	Battery assy	1	\$ 150.00	\$ 150.00
4	Radiator coolant	1	\$ 80.00	\$ 80.00
5	Front bumper clips	10	\$ 4.50	\$ 45.00
6	Front fender cowling clips	12	\$ 4.50	\$ 54.00
7	Engine under cowling clips	6	\$ 4.50	\$ 27.00
8	Front licence plate & frame	1	\$ 55.00	\$ 55.00
9	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 616.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and replace radiator. To perform pressure test and check cooling system functionality.	1	\$ 200.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
5	To remove and replace a/c condenser. To recharge system & check a/c functionality.	1.25	\$ 150.00
6	To align rear chassis frame and to conduct chassis alignment on Car-O-Liner.	1.5	\$ 300.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,400.00

Estimate Grand Total	\$ 18,131.60
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: