

Kg

CHOON HOCK MOTOR TRADING CO

12 May 2021

Not Authorized
61 Sing @ 2850/h
Purvey After Rain
4 days

ESTIMATE REPAIR BILL ON GBC9856Z TOYOTA DYNA

1 pce front headlamp RH	Ln	\$ 845.00	✓
1 pce front bumper assy.	Bu	\$ 555.90	✓
1 pce front door RH	Bd	\$1,580.00	✓
1 pce front door lower hinge RH	L	\$ 60.00	X
1 pce step panel RH	Wdl Ln	\$ 102.00	✓
1 pce front grille assy.	m3cm	\$ 280.00	✓

258

S/NETT

1 pce sticker - company address	Ln	\$ 20.00	✓
Remove door's fittings, refit		\$ 100.00	60h
Wirings		\$ 120.00	20l
Panel beating		\$ 800.00	400l
Spray painting		\$ 800.00	550l
Rustproofing		\$ 80.00	30l
Total amount :		\$ 5,342.90	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to information
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
Tel: (65) 64530778 Email: choonhockmotor@gmail.com