

# RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd  
Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875  
Email: claims@rico60.com  
Tel: 6286 6060 Fax : 6286 7060

## RICO Office Use Only

|          |      |
|----------|------|
| Parts -% |      |
| SN       |      |
| Labour   |      |
| Total    |      |
| Lump Sum |      |
| ERV      | 14K\ |

|                             |
|-----------------------------|
| TO: AIG                     |
| Vehicle No : SMM 6644 E     |
| Make & Model : VOLVO S60 T5 |
| DATE: 10/5/2021             |

Lkr

| No. | DESCRIPTION - PARTS                | QTY | UNIT PRICE  | PRICE                      |
|-----|------------------------------------|-----|-------------|----------------------------|
| 1   | BONNET                             | 1   | \$ 2,245.00 | \$ <del>bt</del> 2,245.00  |
| 2   | BONNET INSULATOR                   | 1   | \$ 421.00   | \$ <del>ht</del> 421.00    |
| 3   | BONNET DAMPER                      | 1   | \$ 184.00   | \$ X 184.00                |
| 4   | BONNET LOCK RH                     | 1   | \$ 441.00   | \$ X 441.00                |
| 5   | FRONT BUMPER                       | 1   | \$ 3,548.00 | \$ <del>de</del> 3,548.00  |
| 6   | FRONT BUMPER SIDE RETAINER         | 1   | \$ 185.00   | \$ <del>de</del> 185.00    |
| 7   | FRONT BUMPER SIDE GARNISH (INNER)  | 1   | \$ 145.00   | \$ <del>ht</del> 145.00    |
| 8   | FRONT BUMPER LOWER CENTER          | 1   | \$ 877.00   | \$ <del>aut</del> 877.00   |
| 9   | FRONT BUMPER TOW COVER             | 1   | \$ 65.00    | \$ X 65.00                 |
| 10  | FRONT BUMPER FOG LAMP LED RH       | 1   | \$ 1,254.00 | \$ <del>one</del> 1,254.00 |
| 11  | FRONT BUMPER FOG LAMP COVER RH     | 1   | \$ 217.00   | \$ X 217.00                |
| 12  | FRONT BUMPER LOWER GRILLE          | 1   | \$ 485.00   | \$ <del>ene</del> 485.00   |
| 13  | FRONT BUMPER LOWER UNDER COVER     | 1   | \$ 652.00   | \$ <del>ht</del> 652.00    |
| 14  | FRONT BUMPER REINFRONT             | 1   | \$ 1,154.00 | \$ <del>ht</del> 1,154.00  |
| 15  | FRONT BUMPER REINFRONT GARNISH     | 1   | \$ 351.00   | \$ <del>de</del> 351.00    |
| 16  | FRONT WIRE HARNESS                 | 1   | \$ 845.00   | \$ X 845.00                |
| 17  | HEAD LAMP RH                       | 1   | \$ 2,458.00 | \$ <del>en</del> 2,458.00  |
| 18  | HEAD LAMP NOZER RH                 | 1   | \$ 245.00   | \$ <del>en</del> 245.00    |
| 19  | HEAD LAMP NOZER PIPE SET           | 1   | \$ 221.00   | \$ <del>de</del> 221.00    |
| 20  | HEAD LAMP BOTTOM REATAINER RH      | 1   | \$ 200.00   | \$ X 200.00                |
| 21  | FRONT SUPPORT PANEL ASSY           | 1   | \$ 1,845.00 | \$ <del>one</del> 1,845.00 |
| 22  | AIRCON CONDENSOR AIR ARCH TOP RH   | 1   | \$ 121.00   | \$ <del>de</del> 121.00    |
| 23  | AIRCON CONDENSOR AIR ARCH LOWER RH | 1   | \$ 121.00   | \$ <del>de</del> 121.00    |
| 24  | TUBOR COOLER                       | 1   | \$ 2,412.00 | \$ <del>del</del> 2,412.00 |
| 25  | FRONT GRILLE                       | 1   | \$ 852.00   | \$ <del>de</del> 852.00    |
| 26  | FRONT GRILLE LOGO                  | 1   | \$ 177.20   | \$ <del>en</del> 177.20    |

|    |                              |   |                      |                       |
|----|------------------------------|---|----------------------|-----------------------|
| 27 | FRONT FENDER RH              | 1 | \$ 1,255.00          | \$ <i>bt</i> 1,255.00 |
| 28 | FRONT FENDER INNER SHILED RH | 1 | \$ 299.00            | \$ <i>de</i> 299.00   |
| 29 | FRONT ABSORBER RH            | 1 | \$ 1,120.00          | \$ <i>x</i> 1,120.00  |
| 30 | FRONT LOWER ARM RH           | 1 | \$ 332.00            | \$ <i>x</i> 332.00    |
| 31 | FRONT KNUCKLE ARM RH         | 1 | \$ 1,078.00          | \$ <i>x</i> 1,078.00  |
| 32 | FRONT WHEEL BEARING RH       | 1 | \$ 479.00            | \$ <i>x</i> 479.00    |
| 33 | FRONT ORIGINAL RIM RH        | 1 | \$ 2,214.00          | \$ <i>x</i> 2,214.00  |
|    |                              |   | <b>Subtotal :</b>    | <b>\$ 25,207.20</b>   |
|    |                              |   | <b>Less 10%</b>      | <b>\$ 2,520.72</b>    |
|    |                              |   | <b>Parts Total :</b> | <b>\$ 22,686.48</b>   |

| NO. | SPECIAL NETT                   | QTY | UNIT PRICE | PRICE                |
|-----|--------------------------------|-----|------------|----------------------|
| 1   | FRONT BUMPER CLIP              | 1   | \$ 60.00   | \$ <i>300g</i> 60.00 |
| 2   | BONNET INSULATOR CLIPS         | 1   | \$ 50.00   | \$ <i>x</i> 50.00    |
| 3   | FRONT FENDER INNER SHIELD CLIP | 1   | \$ 50.00   | \$ <i>100g</i> 50.00 |
| 4   | HEAD LAMP BULB SET             | 1   | \$ 60.00   | \$ <i>x</i> 60.00    |
|     |                                |     |            | <b>\$ 220.00</b>     |

| LABOUR                                                                |            |    | PRICE              |
|-----------------------------------------------------------------------|------------|----|--------------------|
| PANEL BEATING, REMOVAL AND REPLACING PARTS                            | <i>700</i> | \$ | 1,400.00           |
| TO SPRAY PAINT AFFECTED AREA                                          | <i>600</i> | \$ | 1,400.00           |
| TO SPRAY TUFF COAT                                                    | <i>30</i>  | \$ | 200.00             |
| TO REMOVE AND REFIX FRONT UNDERCARRIAGE                               | <i>x</i>   | \$ | 600.00             |
| WIRING, BULB CHECKING                                                 | <i>30</i>  | \$ | 100.00             |
| COODING PROGRAMS HEAD LAMP                                            | <i>x</i>   | \$ | 600.00             |
| FOUR WHEEL ALIGMENT                                                   | <i>x</i>   | \$ | 100.00             |
| REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST | <i>100</i> | \$ | 120.00             |
| REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS                    | <i>100</i> | \$ | 150.00             |
| <b>LABOUR TOTAL</b>                                                   |            |    | <b>\$ 4,670.00</b> |

|                       |  |                          |                     |
|-----------------------|--|--------------------------|---------------------|
| <i>Tanah 97495449</i> |  | <b>Total Parts Cost</b>  | <b>\$ 22,906.48</b> |
| <i>WP 12/5/21</i>     |  | <b>Total Labour Cost</b> | <b>\$ 4,670.00</b>  |
|                       |  | <b>Total Repair Cost</b> | <b>\$ 27,576.48</b> |

*L/S Resurvey after repair  
fempkin @ khawkhaw  
06 days*

- LKK Auto Consultants hereby notify the Repairer of the following:**
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**APPROVED DETAILS**

**NO. OF WORKING DAYS  
PART BY PART OR LUMP SUM  
DATE & TIME OF SURVEY  
SURVEYED BY  
CONTACT NUMBER  
FAX NUMBER**