



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

Lkk.

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	14K1

TO: AIG
Vehicle No : SMM 6644 E
Make & Model : VOLVO S60 T5
DATE: 10/5/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BONNET	1	\$ 2,245.00	\$ bt 2,245.00
2	BONNET INSULATOR	1	\$ 421.00	\$ ht 421.00
3	BONNET DAMPER	1	\$ 184.00	\$ x nh 184.00
4	BONNET LOCK RH	1	\$ 441.00	\$ x nh 441.00
5	FRONT BUMPER	1	\$ 3,548.00	\$ de 3,548.00
6	FRONT BUMPER SIDE RETAINER	1	\$ 185.00	\$ de 185.00
7	FRONT BUMPER SIDE GARNISH (INNER)	1	\$ 145.00	\$ ht 145.00
8	FRONT BUMPER LOWER CENTER	1	\$ 877.00	\$ ht 877.00
9	FRONT BUMPER TOW COVER	1	\$ 65.00	\$ x nh 65.00
10	FRONT BUMPER FOG LAMP LED RH	1	\$ 1,254.00	\$ ht 1,254.00
11	FRONT BUMPER FOG LAMP COVER RH	1	\$ 217.00	\$ x nh 217.00
12	FRONT BUMPER LOWER GRILLE	1	\$ 485.00	\$ ht 485.00
13	FRONT BUMPER LOWER UNDER COVER	1	\$ 652.00	\$ ht 652.00
14	FRONT BUMPER REINFRONT	1	\$ 1,154.00	\$ ht 1,154.00
15	FRONT BUMPER REINFRONT GARNISH	1	\$ 351.00	\$ de 351.00
16	FRONT WIRE HARNESS	1	\$ 845.00	\$ x nh 845.00
17	HEAD LAMP RH	1	\$ 2,458.00	\$ ht 2,458.00
18	HEAD LAMP NOZER RH	1	\$ 245.00	\$ ht 245.00
19	HEAD LAMP NOZER PIPE SET	1	\$ 221.00	\$ de 221.00
20	HEAD LAMP BOTTOM REATAINER RH	1	\$ 200.00	\$ x nh 200.00
21	FRONT SUPPORT PANEL ASSY	1	\$ 1,845.00	\$ ht 1,845.00
22	AIRCON CONDENSOR AIR ARCH TOP RH	1	\$ 121.00	\$ de 121.00
23	AIRCON CONDENSOR AIR ARCH LOWER RH	1	\$ 121.00	\$ de 121.00
24	TUBOR COOLER	1	\$ 2,412.00	\$ ht 2,412.00
25	FRONT GRILLE	1	\$ 852.00	\$ ht 852.00
26	FRONT GRILLE LOGO	1	\$ 177.20	\$ ht 177.20

nnx

27	FRONT FENDER RH	981.95	1	\$ 1,255.00	\$ bt 1,255.00
28	FRONT FENDER INNER SHILED RH	214.58	1	\$ 299.00	\$ de 299.00
29	FRONT ABSORBER RH		1	\$ 1,120.00	\$ x 1,120.00
30	FRONT LOWER ARM RH		1	\$ 332.00	\$ x 332.00
31	FRONT KNUCKLE ARM RH		1	\$ 1,078.00	\$ x 1,078.00
32	FRONT WHEEL BEARING RH		1	\$ 479.00	\$ x 479.00
33	FRONT ORIGINAL RIM RH		1	\$ 2,214.00	\$ x 2,214.00

14940.33

13446.30

Subtotal : \$ 25,207.20

Less 10% \$ 2,520.72

Parts Total : \$ 22,686.48

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER CLIP	1	\$ 60.00	\$ 3000 60.00
2	BONNET INSULATOR CLIPS	1	\$ 50.00	\$ xnn 50.00
3	FRONT FENDER INNER SHIELD CLIP	1	\$ 50.00	\$ 1000 50.00
4	HEAD LAMP BULB SET	1	\$ 60.00	\$ xnn 60.00

40

\$ 220.00

LABOUR

PRICE

PANEL BEATING, REMOVAL AND REPLACING PARTS	700	\$ 1,400.00
TO SPRAY PAINT AFFECTED AREA	600	\$ 1,400.00
TO SPRAY TUFF COAT	30	\$ 200.00
TO REMOVE AND REFIX FRONT UNDERCARRIAGE	nn x	\$ 600.00
WIRING, BULB CHECKING	30	\$ 100.00
COODING PROGRAMS HEAD LAMP	nn x	\$ 600.00
FOUR WHEEL ALIGMENT	nn x	\$ 100.00
REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	100	\$ 120.00
REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	100	\$ 150.00

13446.30

40

LABOUR TOTAL \$ 4,670.00

1560

1560

15045.30
45812.000

Tanphuc 97495749
- VLP 12/5/21

06 days

1/5 Resurvey after repair
fempin @ (Whanbun
06 days

Total Parts Cost \$ 22,906.48

Total Labour Cost \$ 4,670.00

Total Repair Cost \$ 27,576.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: