



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN KOK SIONG (CHEN GUOXIONG) Reg No/Reg Date SML7583X*KC17/ 03/06/201 Date In/Mileage / 0 Chassis No KNAF1416MK5044407 Engine No G4FGKH737213 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim CR5 / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	11/05/2021/ 12:58	QUE	289 / Patrick Lee	33259		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							420 800.00
REPLACE FRT BUMPER & AFFECTED AREAS							480 250.00
E PNT98000							100.00 X
REPSRAY ON FRT BUMPER & AFFECTED AREAS							
E PNT88000							30 80.00
REMOVE & INSTALL RADIATOR & CONDENSER TO FACILITATE REPAIR							
A 54900099							120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							80.00 X
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							20 50.00
TO TOP UP A/C GAS AND CHECK A/C CONDITION							
M SUNDRY							
SUNDRIES				1.00	675.00	20.00	540.00
M CARRIER ASSY-FRONT END MODULE				1.00	497.00	20.00	397.60
M BEAM COMPLETE-FR BUMPER				1.00	633.00	20.00	506.40
M COVER-FR BUMPER				1.00	262.00	20.00	209.60
M GRILLE-FRONT BUMPER				1.00	223.00	20.00	178.40
M GRILLE ASSY-RADIATOR				1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,LH				1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY				1.00	12.00	20.00	9.60
M COVER-DAYTIME RUNNING LIGHT,LH				1.00	32.00	20.00	25.60
M ORNAMENT-KIA NO.115				1.00	1040.00	20.00	832.00
M LAMP ASSY-HEAD,LH							

Estimate

Steve (CLKK)

SURVEYOR NAME: Steve (CLKK)

SURVEYOR SIGNATURE: 11/5/21, 3-30 pm

DATE: 00- N-1 AL

REMARKS: EX111-1

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 11/5/21, 3:30 pm

DATE: 00-M-1 PL

REMARKS: EXHIBIT - 1

Confirm &amp; accepted by

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be made

Authorized signatory and company stamp

3 dys

7% GST on 4375.20  
Total Payable 4,681.46

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.